Reserve Study Update Brandy Creek CDD Update 2020/2021 St. Augustine, Florida



Prepared for FY 2020 Report Date: July 7, 2020





July 7, 2020

Mr. Jim Oliver, District Manager Governmental Management Services 475 West Town Place, Suite 114 St. Augustine, Florida 32092

Re: Brandy Creek CDD Update 2020/2021

Dear Mr. Oliver:

Community Advisors is pleased to provide this Revised Reserve Study report for the above referenced Association. We have completed the adjustments you requested and have updated your funding plan. We recommend updating your study every 3 years to keep your information current with changing replacement cost, interest and inflation rates.

It has been a pleasure serving you and please let me know if you have any questions or concerns.

Respectively submitted,

CRShamarl

Charles R. Sheppard RS PRA CCI

Professional Reserve Analyst 10459 Hunters Creek Court

Jacksonville, Fl. 32256 (904) 303-3275

www.communityadvisors.com







TABLE OF CONTENTS

EXECUTIVE SUMMARY	
Executive Summary	1-1
Current Funding Projection	
Current Funding Projection vs Fully Funded Plan	1-3
FUNDING PLAN	
Threshold Funded Plan	2-1
Recommended Funding Plan Chart	2-2
Alternate Funding Projection	2-3
Alternate Funding Model VS Fully Funded	
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	
COMPONENT INVENTORY	
Condition Assessment	5-1
Component Inventory	5-3
Component Detail Index	
Component Detail	
DISCLOSURERS & INFORMATION	
Methodology & Information	6-1
Terms of Service	6-2
Definitions	6-3

Brandy Creek CDD Update 2020/2021

St. Augustine, Florida **Executive Summary**

Report Date	July 7, 2020
Account Number	1022-5
Version	3
Budget Year Beginning	October 1, 2020
Budget Year Ending	September 30, 2021
Total Units	583

Report Parameters									
Inflation	2.50%								
Annual Assessment Increase	3.00%								
Interest Rate on Reserve Deposit	1.50%								
2020 Beginning Balance	\$200,000								

PROPERTY INFORMATION

Date of Completion: February 1, 2005Date of site visit: February 28, 2020

Components Included: 98

• Current replacement cost: \$1,381,040

FINANCIAL INFORMATION

- Level of Service: Level II Reserve Study Update and Site Visit
- Funding Method: The Cash Flow Method
- Funding Goal: Adequate funding with moderate contributions
- Fully Funded Reserve Balance: \$736,156.
- Current funding Plan: The community begins the study year 27% fully funded. Contributions of \$65,000 for year one with annual increases of 3% does not provide adequate component funding beginning in FY 2027
- Recommend Funding Contribution: Annual contribution of \$99,636 provides adequate funding assuming no unknown construction defects are present, regular preventative maintenance is performed and this study is updated regularly
- Alternate Funding Plan: Provides adequate funding with a larger increase at FY 21-22 with moderate increases in subsequent years.

Threshold Funding Model Summary of Calculations

Required Annual Contribution \$99,635.74
\$170.90 per unit annually


Average Net Annual Interest Earned \$3,805.74

Total Annual Allocation to Reserves \$103,441.48
\$177.43 per unit annually

Brandy Creek CDD Update 2020/2021 Current Funding Projection

Beginning Balance: \$200,000

υ		,			Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
20-21	1,381,040	65,000	3,286	45,920	222,366	800,472	28%
21-22	1,400,192	66,950	3,788	36,785	256,319	879,809	29%
22-23	1,435,196	68,958	3,149	115,329	213,097	883,494	24%
23-24	1,471,076	71,027	3,931	22,050	266,005	985,654	27%
24-25	1,507,853	73,158	1,693	226,326	114,530	884,307	13%
25-26	1,545,549	75,353	2,130	47,859	144,155	965,898	15%
26-27	1,579,549	77,613	2,563	50,899	173,432	1,049,125	17%
27-28	1,619,038	79,942	274	235,102	18,546	948,721	2%
28-29	1,659,514	82,340	880	42,191	59,576	1,046,398	6%
29-30	1,701,002	84,810		232,910	-88,524	954,078	
30-31	1,743,527	87,355		72,688	-73,858	1,024,934	
31-32	1,755,625	89,975		47,466	-31,349	1,126,452	
32-33	1,799,516	92,674		267,447	-206,121	1,008,142	
33-34	1,844,504	95,455		27,570	-138,237	1,135,938	
34-35	1,890,616	98,318		399,704	-439,623	888,764	
35-36	1,937,882	101,268		63,094	-401,449	983,790	
36-37	1,986,329	104,306		32,273	-329,416	1,116,219	
37-38	2,035,987	107,435		298,700	-520,680	982,394	
38-39	2,086,886	110,658		27,294	-437,316	1,127,025	
39-40	2,139,059	113,978		175,334	-498,672	1,127,233	
40-41	2,192,535	117,397		104,282	-485,556	1,196,342	
41-42	2,201,160	120,919		41,788	-406,425	1,340,956	
42-43	2,256,189	124,547		578,949	-860,827	942,533	
43-44	2,312,594	128,283		86,865	-819,409	1,042,573	
44-45	2,370,408	132,132		236,111	-923,388	996,275	
45-46	2,429,669	136,096		78,763	-866,056	1,114,342	
46-47	2,490,410	140,178		33,255	-759,132	1,286,353	
47-48	2,552,671	144,384		237,164	-851,913	1,258,114	
48-49	2,616,487	148,715		87,466	-790,664	1,387,177	
49-50	2,681,900	153,177		83,878	-721,365	1,527,825	




This chart illustrates the current funding plan performance.

Brandy Creek CDD Update 2020/2021 Threshold Funded Plan

Beginning Balance: \$200,000

					Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
20-21	1,381,040	99,636	3,806	45,920	257,521	800,472	32%
21-22	1,400,192	102,625	4,850	36,785	328,212	879,809	37%
22-23	1,435,196	105,704	4,779	115,329	323,365	883,494	37%
23-24	1,471,076	108,875	6,153	22,050	416,342	985,654	42%
24-25	1,507,853	112,141	4,532	226,326	306,689	884,307	35%
25-26	1,545,549	115,505	5,615	47,859	379,951	965,898	39%
26-27	1,579,549	118,970	6,720	50,899	454,742	1,049,125	43%
27-28	1,619,038	122,539	5,133	235,102	347,313	948,721	37%
28-29	1,659,514	126,216	6,470	42,191	437,808	1,046,398	42%
29-30	1,701,002	130,002	5,023	232,910	339,923	954,078	36%
30-31	1,743,527	133,902	6,017	72,688	407,153	1,024,934	40%
31-32	1,755,625	137,919	7,464	47,466	505,071	1,126,452	45%
32-33	1,799,516	142,057	5,695	267,447	385,375	1,008,142	38%
33-34	1,844,504	146,318	7,562	27,570	511,685	1,135,938	45%
34-35	1,890,616	150,708	3,940	399,704	266,630	888,764	30%
35-36	1,937,882	155,229	5,381	63,094	364,147	983,790	37%
36-37	1,986,329	159,886	7,376	32,273	499,136	1,116,219	45%
37-38	2,035,987	164,683	5,477	298,700	370,596	982,394	38%
38-39	2,086,886	169,623	7,694	27,294	520,619	1,127,025	46%
39-40	2,139,059	174,712	7,800	175,334	527,797	1,127,233	47%
40-41	2,192,535	179,953	9,052	104,282	612,521	1,196,342	51%
41-42	2,201,160	185,352	11,341	41,788	767,426	1,340,956	57%
42-43	2,256,189	190,912	5,691	578,949	385,080	942,533	41%
43-44	2,312,594	196,640	7,423	86,865	502,278	1,042,573	48%
44-45	2,370,408	202,539	7,031	236,111	475,737	996,275	48%
45-46	2,429,669	208,615	9,084	78,763	614,673	1,114,342	55%
46-47	2,490,410	214,874	11,944	33,255	808,236	1,286,353	63%
47-48	2,552,671	221,320	11,886	237,164	804,277	1,258,114	64%
48-49	2,616,487	227,959	14,172	87,466	958,942	1,387,177	69%
49-50	2,681,900	234,798	16,648	83,878	1,126,510	1,527,825	74%




This chart illustrates the recommended annual balances, threshold plan contributions or assessments with annual expenditures. Moderately increasing assessments maintain adequate funding with minimum annual balances.

Brandy Creek CDD Update 2020/2021 Alternate Funding Projection

Beginning Balance: \$200,000

υ		,			Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
20-21	1,381,040	65,000	3,286	45,920	222,366	800,472	28%
21-22	1,400,192	102,000	4,314	36,785	291,895	879,809	33%
22-23	1,435,196	105,060	4,224	115,329	285,850	883,494	32%
23-24	1,471,076	108,212	5,580	22,050	377,591	985,654	38%
24-25	1,507,853	111,458	3,941	226,326	266,665	884,307	30%
25-26	1,545,549	114,802	5,004	47,859	338,612	965,898	35%
26-27	1,579,549	118,246	6,089	50,899	412,049	1,049,125	39%
27-28	1,619,038	121,793	4,481	235,102	303,221	948,721	32%
28-29	1,659,514	125,447	5,797	42,191	392,275	1,046,398	37%
29-30	1,701,002	129,211	4,329	232,910	292,903	954,078	31%
30-31	1,743,527	133,087	5,300	72,688	358,601	1,024,934	35%
31-32	1,755,625	137,079	6,723	47,466	454,938	1,126,452	40%
32-33	1,799,516	141,192	4,930	267,447	333,613	1,008,142	33%
33-34	1,844,504	145,428	6,772	27,570	458,242	1,135,938	40%
34-35	1,890,616	149,790	3,125	399,704	211,454	888,764	24%
35-36	1,937,882	154,284	4,540	63,094	307,184	983,790	31%
36-37	1,986,329	158,913	6,507	32,273	440,331	1,116,219	39%
37-38	2,035,987	163,680	4,580	298,700	309,891	982,394	32%
38-39	2,086,886	168,590	6,768	27,294	457,955	1,127,025	41%
39-40	2,139,059	173,648	6,844	175,334	463,113	1,127,233	41%
40-41	2,192,535	178,858	8,065	104,282	545,755	1,196,342	46%
41-42	2,201,160	184,223	10,323	41,788	698,513	1,340,956	52%
42-43	2,256,189	189,750	4,640	578,949	313,954	942,533	33%
43-44	2,312,594	195,443	6,338	86,865	428,870	1,042,573	41%
44-45	2,370,408	201,306	5,911	236,111	399,975	996,275	40%
45-46	2,429,669	207,345	7,928	78,763	536,486	1,114,342	48%
46-47	2,490,410	213,565	10,752	33,255	727,548	1,286,353	57%
47-48	2,552,671	219,972	10,655	237,164	721,012	1,258,114	57%
48-49	2,616,487	226,571	12,902	87,466	873,018	1,387,177	63%
49-50	2,681,900	233,369	15,338	83,878	1,037,846	1,527,825	68%



Alternate Funding Plan Balances, expenditures and assessments are shown here to illustrate fund performance.

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	
Beginning Balance Annual Assessment Interest Earned	200,000 99,636 3,806	257,521 102,625 4,850	328,212 105,704 4,779	323,365 108,875 6,153	416,342 112,141 4,532	306,689 115,505 5,615	379,951 118,970 6,720	454,742 122,539 5,133	347,313 126,216 6,470	437,808 130,002 5,023	
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	45,920 800,472 257,521	36,785 879,809 328,212	115,329 883,494 323,365	22,050 985,654 416,342	226,326 884,307 306,689	47,859 965,898 379,951	50,899 1,049,125 454,742	235,102 948,721 347,313	42,191 1,046,398 437,808	232,910 954,078 339,923	
Description Phase I - Misc.Site Components											
Asphalt Mill & Overlay 1 1/2" - Parking Lot Asphalt Seal Coat - Parking Lot				3,549				3,918		37,046	
Concrete Curb Allowance at Paving Concrete Pavers - Parking Lot Concrete Sidewalk Repair/Replace Allowance										3,122 23,579	
Monument Sign North - Refurbish Allowance Pond Fountain	2,000	3,075				2,263				1,873	
Wood Retaining Wall - Pond Phase I - Misc.Site Components Total:	2,000	3,075		3,549		2,263		3,918		65,620	_
Phase I - Misc. Site Furnishings	,	,		,		,		,		,	
Benches/Trash Cans/ Etc Allow (1 year cycle) Phase I - Misc. Site Furnishings Total:		1,025 1,025	1,051 1,051	1,077 1,077	1,104 1,104	1,131 1,131	1,160 1,160	1,189 1,189	1,218 1,218	1,249 1,249	
Phase I - Fencing & Gates											
Aluminun Fence 4 ft Pool Chain Link Fence - Tennis Court							8,802			43,369	
Dumpster Enclosure Gates Phase I - Fencing & Gates Total:							8,802			2,997 46,367	_
Phase I - Site Lighting							-,			-,	
Light Poles - Basketball Court Light Poles - Parking Lot										7,493 8,742	
Light Poles - Pool Deck Light Poles - Tennis Court							4,175			22,480	

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Phase I - Site Lighting continued										
Pendent Lights - Bld Patio										6,494
Phase I - Site Lighting Total:							4,175			45,209
Phase I - Misc. Bld Components										
Fitness Restrooms Renovation Allowance						11,314				
Pool Restrooms Renovation Allowance					33,114	11,514				
Phase I - Misc. Bld Components Total:					33,114	11,314				
<u>-</u>					33,114	11,517				
Phase I - Roofing										
Standing Seam Metal Roof - Clubhouse										
Standing Seam Metal Roof - Maintenance Bld										
Phase I - Roofing Total:										
Phase I - Exterior Painting										
Buildings/Wood Ceilings							16,236			
Maintenance Building							-,	5,706		
Phase I - Exterior Painting Total:							16,236	5,706		
Dhosa I. Elecuina/Interior Einiches										
Phase I - Flooring/Interior Finishes										
Laminated Wood Flooring - Fitness Center										
Phase I - Flooring/Interior Finishes Total:										
Phase I - Furniture, Fixtures & Equipment										
Fitness Equip. Partial Replace Allowance (1 yea	3,500	3,587	3,677	3,769	3,863	3,960	4,059	4,160	4,264	4,371
Fitness Equipment Replacement Allowance										
Fitness Room TV's	1,200					1,358				
Golf Cart										
Office Furniture/Computers						2,489				
Pool Furniture (Full Replacement)					44,153					
Pool Furniture Partial Replace (1 year cycle)	2,000	2,050	2,101	2,154	2,208	2,263	2,319	2,377	2,437	2,498
Phase I - Furniture, Fixtures & Equipment Total:	6,700	5,637	5,778	5,923	50,223	10,070	6,378	6,538	6,701	6,869

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Phase I - Mechanical Systems										
Heat Pump - Fitness Center 3 Ton										
Heat Pump - Office 1.5 Ton		4,612								
Water Coolers						3,055				
Phase I - Mechanical Systems Total:		4,612				3,055				
Phase I - Playground										
Play Equipment Allowance					44,153					
Post Swing 2 Bay			6.610					4,517		
Shade Structure Fabric - Playground Shade Structure Frame/Fabric - Playground			6,619							
Phase I - Playground Total:			6,619		44,153			4,517		
• •			0,017		44,133			4,517		
Phase I - Tennis Court										
Rebound Wall/Deck Refurbishment Allowance			2,101					7.565		
Tennis Court Resurfacing (color coat) Phase I - Tennis Court Total:			6,686					7,565		
Phase 1 - Tennis Court Total:			8,787					7,565		
Phase I - Outdoor Fitness Trail										
Outdoor Fitness Equipment (phase 1)						4,526				
Outdoor Fitness Equipment (phase 1)								2 255		
Renovation Allowance Track Repair/ Surface R Phase I - Outdoor Fitness Trail Total:						4.500		2,377		
Phase 1 - Outdoor Fitness Trail Total:						4,526		2,377		
Phase I - Basketball Court										
Basketball Court Resurfacing (color coat)	3,180							3,780		
Basketball Pole & Backboard	- 100					2,263		• = 0.0		
Phase I - Basketball Court Total:	3,180					2,263		3,780		
Phase I - Swimming Pool										
Concrete Pavers - Pool Deck										
Filtration Equipment Refurbish Allowance										
Pool Filtration Repair/Replace Allowance (1 yea	2,000	2,050	2,101	2,154	2,208	2,263	2,319	2,377	2,437	2,498
Pool Lift Pool Play Equipment					37,530		3,711			
roof riay Equipment					37,330					

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Phase I - Swimming Pool continued										
Pool Repair/Resurfacing/Tile								112,830		
Shade Structure Fabric			2,521							
Shade Structure Frame/Fabric										
Shade Structures Fabric	4,800									
Shade Structures Frame/Fabric		• • • •						11.5.0.5		9,991
Phase I - Swimming Pool Total:	6,800	2,050	4,623	2,154	39,737	2,263	6,030	115,207	2,437	12,489
Phase II - Misc Site Components										
Asphalt Mill & Overlay 1 1/2" - Parking Lot										
Asphalt Seal Coat - Parking Lot				1,809				1,997		
Concrete Curb								3,617		
Concrete Pavers										
Concrete Sidewalk Repair/Replace Allowance										
East Monument Sign Refurbish Allowance										
Exterior Signage				4.000				5,943		
Phase II - Misc Site Components Total:				1,809				11,558		
Phase II - Fencing & Gates										
Aluminun Fence 4 ft Pool										43,369
Vinyl Privacy Fence - Pool Equipment										
Phase II - Fencing & Gates Total:										43,369
Phase II - Site Lighting										
Light Poles - Basketball Court										
Light Poles - Parking Lot										
Light Poles - Playgound										
Phase II - Site Lighting Total:										
Phase II - Misc. Bld Components										
Phone H. Miss Bld Common and Tatal										
Phase II - Misc. Bld Components Total:										

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Phase II - Roofing										
Standing Seam Metal Roof - CH/Restroom Bld										
Phase II - Roofing Total:										
Phase II - Exterior Painting										
Buildings/Pergola					15,387					
Phase II - Exterior Painting Total:					15,387					
Phase II - Flooring/Interior Finishes										
Flooring - Clubhouse	6,240								7,603	
Interior Painting - CH/Restrooms		5,412							6,433	
Laminate Cabinets & Top - Clubhouse										
Phase II - Flooring/Interior Finishes Total:	6,240	5,412							14,036	
Phase II - Furniture, Fixtures, Equipment										
Pool Furniture (Full Replacement)										
Pool Furniture Partial Replace (1 year cycle)	2,000	2,050	2,101	2,154	2,208	2,263	2,319	2,377	2,437	2,498
Phase II - Furniture, Fixtures, Equipment Total:	2,000	2,050	2,101	2,154	2,208	2,263	2,319	2,377	2,437	2,498
Phase II - Mechanical Systems										
HVAC Systems								14,264		
Water Coolers						3,055				
Phase II - Mechanical Systems Total:						3,055		14,264		
Phase II - Playground										
Climber								3,804		
Play Equipment Allowance								35,661		
Post Swing One Bay Phase II - Playground Total:								3,328		
								42,793		
Phase II - Basketball Court										
Basketball Court Resurfacing (color coat)		7,798						0.54	9,270	
Basketball Pole & Backboard Phase II - Basketball Court Total:		7 700						3,566	0.270	
rnase 11 - Basketdan Court 10tai:		7,798						3,566	9,270	

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Phase II - Swimming Pool										
Concrete Pavers - Pool Deck										
Filtration Equipment Refurbishment Allowance										
Pergola Repair Allowance	15,000									
Pool Filtration Repair/Replace Allowance (1 yea	2,000	2,050	2,101	2,154	2,208	2,263	2,319	2,377	2,437	2,498
Pool Lift								3,804		
Pool Pumps & Equipment Allowance	2,000	2,050	2,101	2,154	2,208	2,263	2,319	2,377	2,437	2,498
Pool Repair/Resurfacing/Tile			76,074							
Shade Structures Fabric			5,043							
Shade Structures Frame/Fabric										
Wood Repair/Replace - Pergola										
Phase II - Swimming Pool Total:	19,000	4,100	85,319	4,308	4,415	4,526	4,639	8,559	4,874	4,995
Pocket Park Components										
Benches/Trash Cans/Etc Allow (1 year cycle)		1,025	1,051	1,077	1,104	1,131	1,160	1,189	1,218	1,249
Light Poles										
Picnic Pavilion										
Picnic Tables - Expanded Metal										2,997
Play Equipment Allowance					33,114					
Spring Riders					1,766					
Pocket Park Components Total:		1,025	1,051	1,077	35,984	1,131	1,160	1,189	1,218	4,246
Components Not Included										
Access Control Systen	Unfunded									
Access Control Systen	Unfunded									
Aluminum Flag Poles	Unfunded									
Audio Equipment	Unfunded									
Exterior Decorative Louvers	Unfunded									
Exterior Doors	Unfunded									
Exterior Fireplace & Chimney	Unfunded									
Exterior Siding/Trim	Unfunded									
Exterior Signage	Unfunded									
Fitness Room Ceiling Fans	Unfunded									
Gutters/Downspouts	Unfunded									

	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30
Description										
Components Not Included continued										
Interior Painting - Clubhouse/Restrooms	Unfunded									
Office Carpet & Paint Renovation	Unfunded									
Patio Bar/Sink Phase 1	Unfunded									
Pool Hand Rails	Unfunded									
Pool Shower Poles	Unfunded									
Storm Water Pond Maintenance	Unfunded									
Street Signs	Unfunded									
Tennis Court Net Replacement	Unfunded									
Tennis Court Replacement	Unfunded									
Water Heater	Unfunded									
Windows	Unfunded									
Year Total:	45,920	36,785	115,329	22,050	226,326	47,859	50,899	235,102	42,191	232,910

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Beginning Balance	339,923	407,153	505,071	385,375	511,685	266,630	364,147	499,136	370,596	520,619
Annual Assessment	133,902	137,919	142,057	146,318	150,708	155,229	159,886	164,683	169,623	174,712
Interest Earned	6,017	7,464	5,695	7,562	3,940	5,381	7,376	5,477	7,694	7,800
Expenditures	72,688	47,466	267,447	27,570	399,704	63,094	32,273	298,700	27,294	175,334
Fully Funded Reserves Percent Fully Funded	1,024,934 407,153	1,126,452 505,071	1,008,142 385,375	1,135,938 511,685	888,764 266,630	983,790 364,147	1,116,219 499,136	982,394 370,596	1,127,025 520,619	1,127,233 527,797
Ending Balance	407,133	303,071	363,373	311,003	200,030	304,147	499,130	370,390	320,019	321,191
Description										
Phase I - Misc.Site Components										
Asphalt Mill & Overlay 1 1/2" - Parking Lot										
Asphalt Seal Coat - Parking Lot		4,325				4,774				5,269
Concrete Curb Allowance at Paving										
Concrete Pavers - Parking Lot										
Concrete Sidewalk Repair/Replace Allowance										
Monument Sign North - Refurbish Allowance		3,936								
Pond Fountain	2,560				10 110	2,897				
Wood Retaining Wall - Pond	2.50	0.041			43,669	5 (5 0				7. 040
Phase I - Misc.Site Components Total:	2,560	8,261			43,669	7,670				5,269
Phase I - Misc. Site Furnishings										
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,280	1,312	1,345	1,379	1,413	1,448	1,485	1,522	1,560	1,599
Phase I - Misc. Site Furnishings Total:	1,280	1,312	1,345	1,379	1,413	1,448	1,485	1,522	1,560	1,599
Phase I - Fencing & Gates										
Aluminun Fence 4 ft Pool										
Chain Link Fence - Tennis Court										
Dumpster Enclosure Gates										
Phase I - Fencing & Gates Total:										
Phase I - Site Lighting										
Light Poles - Basketball Court										
Light Poles - Parking Lot										
Light Poles - Pool Deck										
Light Poles - Tennis Court										

Community Advisors Page 3-8

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Phase I - Site Lighting continued										
Pendent Lights - Bld Patio										
Phase I - Site Lighting Total:										
Phase I - Misc. Bld Components										
Fitness Restrooms Renovation Allowance										
Pool Restrooms Renovation Allowance										
Phase I - Misc. Bld Components Total:										
Phase I - Roofing										
Standing Seam Metal Roof - Clubhouse					142,905					
Standing Seam Metal Roof - Maintenance Bld										
Phase I - Roofing Total:					142,905					
Phase I - Exterior Painting										
Buildings/Wood Ceilings					19,782					
Maintenance Building						6,952				
Phase I - Exterior Painting Total:					19,782	6,952				
Phase I - Flooring/Interior Finishes										
Laminated Wood Flooring - Fitness Center	6,508									
Phase I - Flooring/Interior Finishes Total:	6,508									
Phase I - Furniture, Fixtures & Equipment										
Fitness Equip. Partial Replace Allowance (1 yea	4,480	4,592	4,707	4,825	4,945	5,069	5,196	5,326	5,459	5,595
Fitness Equipment Replacement Allowance										
Fitness Room TV's	1,536					1,738				
Golf Cart	0.015	9,447				2.104				
Office Furniture/Computers Pool Furniture (Full Replacement)	2,816					3,186				
Pool Furniture Partial Replace (1 year cycle)	2,560	2,624	2,690	2,757	2,826	2,897	2,969	3,043	3,119	3,197
Phase I - Furniture, Fixtures & Equipment Total:	11,393	16,663	7,397	7,582	7,771	12,890	8,165	8,369	8,578	8,793

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Phase I - Mechanical Systems										
Heat Pump - Fitness Center 3 Ton		7,216								
Heat Pump - Office 1.5 Ton				6,203						
Water Coolers								4,108		
Phase I - Mechanical Systems Total:		7,216		6,203				4,108		
Phase I - Playground										
Play Equipment Allowance										63,946
Post Swing 2 Bay										
Shade Structure Fabric - Playground			8,473							
Shade Structure Frame/Fabric - Playground			18,828							(2.04)
Phase I - Playground Total:			27,301							63,946
Phase I - Tennis Court										
Rebound Wall/Deck Refurbishment Allowance	2,560								3,119	
Tennis Court Resurfacing (color coat)			8,559					9,684		
Phase I - Tennis Court Total:	2,560		8,559					9,684	3,119	
Phase I - Outdoor Fitness Trail										
Outdoor Fitness Equipment (phase 1)										
Outdoor Fitness Equipment (phase 1)	30,722									
Renovation Allowance Track Repair/ Surface R										
Phase I - Outdoor Fitness Trail Total:	30,722									
Phase I - Basketball Court										
Basketball Court Resurfacing (color coat)					4,493					
Basketball Pole & Backboard										
Phase I - Basketball Court Total:					4,493					
Phase I - Swimming Pool										
Concrete Pavers - Pool Deck					96,320					
Filtration Equipment Refurbish Allowance					42,389					
Pool Filtration Repair/Replace Allowance (1 yea Pool Lift	2,560	2,624	2,690	2,757	2,826	2,897	2,969	3,043	3,119	3,197
Pool Play Equipment										

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Phase I - Swimming Pool continued										
Pool Repair/Resurfacing/Tile								144,432		
Shade Structure Fabric			3,228							
Shade Structure Frame/Fabric								12,173		
Shade Structures Fabric	6,144									
Shade Structures Frame/Fabric	_									
Phase I - Swimming Pool Total:	8,705	2,624	5,918	2,757	141,535	2,897	2,969	159,648	3,119	3,197
Phase II - Misc Site Components										
Asphalt Mill & Overlay 1 1/2" - Parking Lot								23,007		
Asphalt Seal Coat - Parking Lot		2,204				2,433				2,686
Concrete Curb										
Concrete Pavers										
Concrete Sidewalk Repair/Replace Allowance								1,522		
East Monument Sign Refurbish Allowance					2,826					
Exterior Signage		2 20 4			• • • • •			24.720		2 (0)
Phase II - Misc Site Components Total:		2,204			2,826	2,433		24,528		2,686
Phase II - Fencing & Gates										
Aluminun Fence 4 ft Pool										
Vinyl Privacy Fence - Pool Equipment										
Phase II - Fencing & Gates Total:										
Phase II - Site Lighting										
Light Poles - Basketball Court								18,259		
Light Poles - Parking Lot								10,651		
Light Poles - Playgound								22,824		
Phase II - Site Lighting Total:								51,735		
Phase II - Misc. Bld Components										
Pool Restrooms Renovation Allowance			26,898							
Phase II - Misc. Bld Components Total:			26,898							

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Phase II - Roofing										
Standing Seam Metal Roof - CH/Restroom Bld										
Phase II - Roofing Total:										
Phase II - Exterior Painting										
Buildings/Pergola			18,748							
Phase II - Exterior Painting Total:			18,748							
Phase II - Flooring/Interior Finishes										
Flooring - Clubhouse							9,263			
Interior Painting - CH/Restrooms			4.226			7,647				
Laminate Cabinets & Top - Clubhouse Phase II - Flooring/Interior Finishes Total:			4,236 4,236			7,647	9,263			
<u> </u>			4,230			7,047	7,20 5			
Phase II - Furniture, Fixtures, Equipment			52.707							
Pool Furniture (Full Replacement) Pool Furniture Partial Replace (1 year cycle)	2,560	2,624	53,796 2,690	2,757	2,826	2,897	2,969	3,043	3,119	3,197
Phase II - Furniture, Fixtures, Equipment Total:	2,560	2,624	56,485	2,757	2,826	2,897	2,969	3,043	3,119	3,197
Phase II - Mechanical Systems	,	,	,	,	,	,	,	,	,	,
HVAC Systems										
Water Coolers								4,108		
Phase II - Mechanical Systems Total:								4,108		
Phase II - Playground										
Climber										
Play Equipment Allowance										
Post Swing One Bay										
Phase II - Playground Total:										
Phase II - Basketball Court										
Basketball Court Resurfacing (color coat)						11,019				
Basketball Pole & Backboard						44.046				
Phase II - Basketball Court Total:						11,019				

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Phase II - Swimming Pool										
Concrete Pavers - Pool Deck										
Filtration Equipment Refurbishment Allowance										
Pergola Repair Allowance										
Pool Filtration Repair/Replace Allowance (1 yea	2,560	2,624	2,690	2,757	2,826	2,897	2,969	3,043	3,119	3,197
Pool Lift	2.7.0	2 (2)	2 600	2 5 5 5	2.024	2.005	2.0.50	2.042	2.110	2.105
Pool Pumps & Equipment Allowance	2,560	2,624	2,690	2,757	2,826	2,897	2,969	3,043	3,119	3,197
Pool Repair/Resurfacing/Tile Shade Structures Fabric			97,381							
Shade Structures Frame/Fabric			6,455					24,346		
Wood Repair/Replace - Pergola								24,340		28,136
Phase II - Swimming Pool Total:	5,120	5,248	109,216	5,514	5,652	5,793	5,938	30,432	6,239	34,531
	0,120	2,2 .0	107,210	0,011	2,022	2,770	2,500	00,102	0,20	0 1,001
Pocket Park Components										
Benches/Trash Cans/Etc Allow (1 year cycle)	1,280	1,312	1,345	1,379	1,413	1,448	1,485	1,522	1,560	1,599
Light Poles					13,847					
Picnic Pavilion Picnic Tobles Expanded Metal					11,572					
Picnic Tables - Expanded Metal Play Equipment Allowance										47,960
Spring Riders										2,558
Pocket Park Components Total:	1,280	1,312	1,345	1,379	26,832	1,448	1,485	1,522	1,560	52,116
<u>-</u>	1,200	1,512	1,545	1,577	20,032	1,440	1,405	1,522	1,500	32,110
Components Not Included										
Access Control Systen	Unfunded									
Access Control Systen	Unfunded									
Aluminum Flag Poles	Unfunded									
Audio Equipment	Unfunded									
Exterior Decorative Louvers	Unfunded									
Exterior Doors	Unfunded									
Exterior Fireplace & Chimney	Unfunded									
Exterior Siding/Trim	Unfunded									
Exterior Signage	Unfunded									
Fitness Room Ceiling Fans	Unfunded									
Gutters/Downspouts	Unfunded									

	30-31	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40
Description										
Components Not Included continued										
Interior Painting - Clubhouse/Restrooms	Unfunded									
Office Carpet & Paint Renovation	Unfunded									
Patio Bar/Sink Phase 1	Unfunded									
Pool Hand Rails	Unfunded									
Pool Shower Poles	Unfunded									
Storm Water Pond Maintenance	Unfunded									
Street Signs	Unfunded									
Tennis Court Net Replacement	Unfunded									
Tennis Court Replacement	Unfunded									
Water Heater	Unfunded									
Windows	Unfunded									
Year Total:	72,688	47,466	267,447	27,570	399,704	63,094	32,273	298,700	27,294	175,334

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Beginning Balance	527,797	612,521	767,426	385,080	502,278	475,737	614,673	808,236	804,277	958,942
Annual Assessment	179,953	185,352	190,912	196,640	202,539	208,615	214,874	221,320	227,959	234,798
Interest Earned	9,052	11,341	5,691	7,423	7,031	9,084	11,944	11,886	14,172	16,648
Expenditures	104,282	41,788	578,949	86,865	236,111	78,763	33,255	237,164	87,466	83,878
Fully Funded Reserves	1,196,342	1,340,956	942,533	1,042,573	996,275	1,114,342	1,286,353	1,258,114	1,387,177	1,527,825
Percent Fully Funded	612,521	767,426	385,080	502,278	475,737	614,673	808,236	804,277	958,942	1,126,510
Ending Balance										
Description										
Phase I - Misc.Site Components										
Asphalt Mill & Overlay 1 1/2" - Parking Lot										
Asphalt Seal Coat - Parking Lot				5,816				6,420		
Concrete Curb Allowance at Paving										
Concrete Pavers - Parking Lot										
Concrete Sidewalk Repair/Replace Allowance										
Monument Sign North - Refurbish Allowance		5,039								
Pond Fountain	3,277					3,708				
Wood Retaining Wall - Pond										
Phase I - Misc.Site Components Total:	3,277	5,039		5,816		3,708		6,420		
Phase I - Misc. Site Furnishings										
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,639	1,680	1,722	1,765	1,809	1,854	1,900	1,948	1,996	2,046
Phase I - Misc. Site Furnishings Total:	1,639	1,680	1,722	1,765	1,809	1,854	1,900	1,948	1,996	2,046
Phase I - Fencing & Gates										
Aluminun Fence 4 ft Pool										
Chain Link Fence - Tennis Court									15,153	
Dumpster Enclosure Gates					4,341					
Phase I - Fencing & Gates Total:					4,341				15,153	
Phase I - Site Lighting										
Light Poles - Basketball Court										
Light Poles - Parking Lot										
Light Poles - Pool Deck									7,187	

Light Poles - Tennis Court

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Phase I - Site Lighting continued										
Pendent Lights - Bld Patio										10,641
Phase I - Site Lighting Total:									7,187	10,641
Phase I - Misc. Bld Components										
Fitness Restrooms Renovation Allowance						18,539				
Pool Restrooms Renovation Allowance					54,262	10.700				
Phase I - Misc. Bld Components Total:					54,262	18,539				
Phase I - Roofing										
Standing Seam Metal Roof - Clubhouse										
Standing Seam Metal Roof - Maintenance Bld				19,852						
Phase I - Roofing Total:				19,852						
Phase I - Exterior Painting										
Buildings/Wood Ceilings			24,102							
Maintenance Building				8,470						
Phase I - Exterior Painting Total:			24,102	8,470						
Phase I - Flooring/Interior Finishes										
Laminated Wood Flooring - Fitness Center						9,425				
Phase I - Flooring/Interior Finishes Total:						9,425				
Phase I - Furniture, Fixtures & Equipment										
Fitness Equip. Partial Replace Allowance (1 yea		5,879	6,025	6,176	6,331	6,489	6,651	6,817	6,988	7,162
Fitness Equipment Replacement Allowance	45,062									
Fitness Room TV's	1,966			12.707		2,225				
Golf Cart Office Furniture/Computers	3,605			12,705		4,079				
Pool Furniture (Full Replacement)	3,003				72,349	4,079				
Pool Furniture Partial Replace (1 year cycle)	3,277	3,359	3,443	3,529	3,617	3,708	3,801	3,896	3,993	4,093
Phase I - Furniture, Fixtures & Equipment Total:	53,910	9,238	9,469	22,411	82,297	16,500	10,452	10,713	10,981	11,255

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Phase I - Mechanical Systems										
Heat Pump - Fitness Center 3 Ton				9,705						
Heat Pump - Office 1.5 Ton						8,343				
Water Coolers										5,525
Phase I - Mechanical Systems Total:				9,705		8,343				5,525
Phase I - Playground										
Play Equipment Allowance										
Post Swing 2 Bay			6,542							
Shade Structure Fabric - Playground			10,846							
Shade Structure Frame/Fabric - Playground										
Phase I - Playground Total:			17,388							
Phase I - Tennis Court										
Rebound Wall/Deck Refurbishment Allowance							3,801			
Tennis Court Resurfacing (color coat)			10,956					12,396		
Phase I - Tennis Court Total:			10,956				3,801	12,396		
Phase I - Outdoor Fitness Trail										
Outdoor Fitness Equipment (phase 1)										
Outdoor Fitness Equipment (phase 1)										
Renovation Allowance Track Repair/ Surface R			3,443							
Phase I - Outdoor Fitness Trail Total:			3,443							
Phase I - Basketball Court										
Basketball Court Resurfacing (color coat)		5,341							6,349	
Basketball Pole & Backboard						3,708				
Phase I - Basketball Court Total:		5,341				3,708			6,349	
Phase I - Swimming Pool										
Concrete Pavers - Pool Deck										
Filtration Equipment Refurbish Allowance										
Pool Filtration Repair/Replace Allowance (1 yea	3,277	3,359	3,443	3,529	3,617	3,708	3,801	3,896	3,993	4,093
Pool Lift		5,375								
Pool Play Equipment					61,497					

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Phase I - Swimming Pool continued										
Pool Repair/Resurfacing/Tile								184,885		
Shade Structure Fabric			4,132							
Shade Structure Frame/Fabric										
Shade Structures Fabric	7,865									
Shade Structures Frame/Fabric										
Phase I - Swimming Pool Total:	11,143	8,734	7,575	3,529	65,114	3,708	3,801	188,781	3,993	4,093
Phase II - Misc Site Components										
Asphalt Mill & Overlay 1 1/2" - Parking Lot										
Asphalt Seal Coat - Parking Lot				2,965				3,272		
Concrete Curb			5,239							
Concrete Pavers			9,641							
Concrete Sidewalk Repair/Replace Allowance										
East Monument Sign Refurbish Allowance										4,093
Exterior Signage			8,608							
Phase II - Misc Site Components Total:			23,487	2,965				3,272		4,093
Phase II - Fencing & Gates										
Aluminun Fence 4 ft Pool										
Vinyl Privacy Fence - Pool Equipment			4,269							
Phase II - Fencing & Gates Total:			4,269							
Phase II - Site Lighting										
Light Poles - Basketball Court										
Light Poles - Parking Lot										
Light Poles - Playgound										
Phase II - Site Lighting Total:										
Phase II - Misc. Bld Components										
Pool Restrooms Renovation Allowance										
Phase II - Misc. Bld Components Total:										

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Phase II - Roofing										
Standing Seam Metal Roof - CH/Restroom Bld			88,661							
Phase II - Roofing Total:			88,661							
Phase II - Exterior Painting										
Buildings/Pergola	22,842								27,831	
Phase II - Exterior Painting Total:	22,842								27,831	
Phase II - Flooring/Interior Finishes										
Flooring - Clubhouse					11,286					
Interior Painting - CH/Restrooms			9,090		,					10,805
Laminate Cabinets & Top - Clubhouse										
Phase II - Flooring/Interior Finishes Total:			9,090		11,286					10,805
Phase II - Furniture, Fixtures, Equipment										
Pool Furniture (Full Replacement)										
Pool Furniture Partial Replace (1 year cycle)	3,277	3,359	3,443	3,529	3,617	3,708	3,801	3,896	3,993	4,093
Phase II - Furniture, Fixtures, Equipment Total:	3,277	3,359	3,443	3,529	3,617	3,708	3,801	3,896	3,993	4,093
Phase II - Mechanical Systems										
HVAC Systems			20,659							
Water Coolers										5,525
Phase II - Mechanical Systems Total:			20,659							5,525
Phase II - Playground										
Climber			5,509							
Play Equipment Allowance			51,647							
Post Swing One Bay			4,820							
Phase II - Playground Total:			61,977							
Phase II - Basketball Court										
Basketball Court Resurfacing (color coat)			13,098							15,569
Basketball Pole & Backboard			5,165							
Phase II - Basketball Court Total:			18,262							15,569

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Phase II - Swimming Pool										
Concrete Pavers - Pool Deck			75,763							
Filtration Equipment Refurbishment Allowance			51,647							
Pergola Repair Allowance										
Pool Filtration Repair/Replace Allowance (1 yea	3,277	3,359	3,443	3,529	3,617	3,708	3,801	3,896	3,993	4,093
Pool Lift			5,509							
Pool Pumps & Equipment Allowance	3,277	3,359	3,443	3,529	3,617	3,708	3,801	3,896	3,993	4,093
Pool Repair/Resurfacing/Tile			124,656							
Shade Structures Fabric			8,264							
Shade Structures Frame/Fabric										
Wood Repair/Replace - Pergola										
Phase II - Swimming Pool Total:	6,554	6,718	272,724	7,058	7,235	7,416	7,601	7,791	7,986	8,186
Pocket Park Components										
Benches/Trash Cans/Etc Allow (1 year cycle)	1,639	1,680	1,722	1,765	1,809	1,854	1,900	1,948	1,996	2,046
Light Poles										
Picnic Pavilion										
Picnic Tables - Expanded Metal					4,341					
Play Equipment Allowance										
Spring Riders										
Pocket Park Components Total:	1,639	1,680	1,722	1,765	6,150	1,854	1,900	1,948	1,996	2,046
Components Not Included										
Access Control Systen	Unfunded									
Access Control Systen	Unfunded									
Aluminum Flag Poles	Unfunded									
Audio Equipment	Unfunded									
Exterior Decorative Louvers	Unfunded									
Exterior Doors	Unfunded									
Exterior Fireplace & Chimney	Unfunded									
Exterior Siding/Trim	Unfunded									
Exterior Signage	Unfunded									
Fitness Room Ceiling Fans	Unfunded									
Gutters/Downspouts	Unfunded									

	40-41	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50
Description										
Components Not Included continued										
Interior Painting - Clubhouse/Restrooms	Unfunded									
Office Carpet & Paint Renovation	Unfunded									
Patio Bar/Sink Phase 1	Unfunded									
Pool Hand Rails	Unfunded									
Pool Shower Poles	Unfunded									
Storm Water Pond Maintenance	Unfunded									
Street Signs	Unfunded									
Tennis Court Net Replacement	Unfunded									
Tennis Court Replacement	Unfunded									
Water Heater	Unfunded									
Windows	Unfunded									
Year Total:	104,282	41,788	578,949	86,865	236,111	78,763	33,255	237,164	87,466	83,878

Description	Expenditures
Replacement Year 20-21	
Phase I - Misc.Site Components	
Pond Fountain	2,000
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	3,500
Fitness Room TV's	1,200
Pool Furniture Partial Replace (1 year cycle)	2,000
Phase I - Basketball Court	
Basketball Court Resurfacing (color coat)	3,180
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,000
Shade Structures Fabric	4,800
Phase II - Flooring/Interior Finishes	
Flooring - Clubhouse	6,240
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,000
Phase II - Swimming Pool	
Pergola Repair Allowance	15,000
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,000
Pool Pumps & Equipment Allowance	2,000
Total for 2020 - 2021	\$45,920
Replacement Year 21-22	
Phase I - Misc.Site Components	
Monument Sign North - Refurbish Allowance	3,075
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,025
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	3,587
Pool Furniture Partial Replace (1 year cycle)	2,050
Phase I - Mechanical Systems	
Heat Pump - Office 1.5 Ton	4,612
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,050

Description	Expenditures
Replacement Year 21-22 continued	
Phase II - Flooring/Interior Finishes	
Interior Painting - CH/Restrooms	5,412
Phase II - Furniture, Fixtures, Equipment Pool Furniture Partial Replace (1 year cycle)	2,050
Phase II - Basketball Court	2,000
Basketball Court Resurfacing (color coat)	7,798
Phase II - Swimming Pool	,
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,050
Pool Pumps & Equipment Allowance	2,050
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,025
Total for 2021 - 2022	\$36,785
Replacement Year 22-23	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,051
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	3,677
Pool Furniture Partial Replace (1 year cycle)	2,101
Phase I - Playground	
Shade Structure Fabric - Playground	6,619
Phase I - Tennis Court	
Rebound Wall/Deck Refurbishment Allowance	2,101
Tennis Court Resurfacing (color coat)	6,686
Phase I - Swimming Pool	2 101
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,101
Shade Structure Fabric	2,521
Phase II - Furniture, Fixtures, Equipment	2 101
Pool Furniture Partial Replace (1 year cycle)	2,101
Phase II - Swimming Pool Pool Filtration Repair/Replace Allowance (1 year cycle)	2,101
Pool Pumps & Equipment Allowance	2,101
Pool Repair/Resurfacing/Tile	76,074
	. 3,3 / 1

Description	Expenditures
Replacement Year 22-23 continued Shade Structures Fabric	5,043
Pocket Park Components Benches/Trash Cans/Etc Allow (1 year cycle)	1,051
Total for 2022 - 2023	\$115,329
Replacement Year 23-24	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	3,549
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,077
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	3,769
Pool Furniture Partial Replace (1 year cycle)	2,154
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,154
Phase II - Misc Site Components	
Asphalt Seal Coat - Parking Lot	1,809
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,154
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,154
Pool Pumps & Equipment Allowance	2,154
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	
Total for 2023 - 2024	\$22,050
Replacement Year 24-25	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,104
Phase I - Misc. Bld Components	
Pool Restrooms Renovation Allowance	33,114
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	3,863

Description	Expenditures
Replacement Year 24-25 continued	
Pool Furniture (Full Replacement)	44,153
Pool Furniture Partial Replace (1 year cycle)	2,208
Phase I - Playground	
Play Equipment Allowance	44,153
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,208
Pool Play Equipment	37,530
Phase II - Exterior Painting	
Buildings/Pergola	15,387
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,208
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,208
Pool Pumps & Equipment Allowance	2,208
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,104
Play Equipment Allowance	33,114
Spring Riders	1,766
Total for 2024 - 2025	\$226,326
Replacement Year 25-26	
Phase I - Misc.Site Components	
Pond Fountain	2,263
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,131
Phase I - Misc. Bld Components	
Fitness Restrooms Renovation Allowance	11,314
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	3,960
Fitness Room TV's	1,358
Office Furniture/Computers	2,489
Pool Furniture Partial Replace (1 year cycle)	2,263
Phase I - Mechanical Systems	
Water Coolers	3,055

Description	Expenditures
Replacement Year 25-26 continued	
Phase I - Outdoor Fitness Trail	
Outdoor Fitness Equipment (phase 1)	4,526
Phase I - Basketball Court	
Basketball Pole & Backboard	2,263
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,263
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,263
Phase II - Mechanical Systems	
Water Coolers	3,055
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,263
Pool Pumps & Equipment Allowance	2,263
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,131
Total for 2025 - 2026	\$47,859
Replacement Year 26-27	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,160
Phase I - Fencing & Gates	
Chain Link Fence - Tennis Court	8,802
Phase I - Site Lighting	
Light Poles - Pool Deck	4,175
Phase I - Exterior Painting	
Buildings/Wood Ceilings	16,236
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,059
Pool Furniture Partial Replace (1 year cycle)	2,319
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,319
Pool Lift	3,711
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,319

Description	Expenditures
Replacement Year 26-27 continued	
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,319
Pool Pumps & Equipment Allowance	2,319
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,160
Total for 2026 - 2027	\$50,899
10441101 2020 2021	\$2.0,0 33
Replacement Year 27-28	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	3,918
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,189
Phase I - Exterior Painting	
Maintenance Building	5,706
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,160
Pool Furniture Partial Replace (1 year cycle)	2,377
Phase I - Playground	
Post Swing 2 Bay	4,517
Phase I - Tennis Court	
Tennis Court Resurfacing (color coat)	7,565
Phase I - Outdoor Fitness Trail	
Renovation Allowance Track Repair/ Surface Replenishment Allowance	2,377
Phase I - Basketball Court	
Basketball Court Resurfacing (color coat)	3,780
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,377
Pool Repair/Resurfacing/Tile	112,830
Phase II - Misc Site Components	
Asphalt Seal Coat - Parking Lot	1,997
Concrete Curb	3,617
Exterior Signage	5,943
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,377

Description	Expenditures
Replacement Year 27-28 continued	
Phase II - Mechanical Systems	
HVAC Systems	14,264
Phase II - Playground	
Climber	3,804
Play Equipment Allowance	35,661
Post Swing One Bay	3,328
Phase II - Basketball Court	
Basketball Pole & Backboard	3,566
Phase II - Swimming Pool	2.255
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,377
Pool Pumps & Equipment Allowance	3,804 2,377
Pool Pumps & Equipment Allowance	2,311
Pocket Park Components Benches/Trash Cans/Etc Allow (1 year cycle)	1,189
	<u> </u>
Total for 2027 - 2028	\$235,102
Replacement Year 28-29	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,218
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,264
Pool Furniture Partial Replace (1 year cycle)	2,437
Phase I - Swimming Pool	2 427
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,437
Phase II - Flooring/Interior Finishes	7.602
Flooring - Clubhouse Interior Painting - CH/Restrooms	7,603 6,433
	0,433
Phase II - Furniture, Fixtures, Equipment Pool Furniture Partial Replace (1 year cycle)	2,437
Phase II - Basketball Court	2,437
Basketball Court Resurfacing (color coat)	9,270
	7,210
Phase II - Swimming Pool Pool Filtration Repair/Replace Allowance (1 year cycle)	2,437
1 0011 Infation Repull/Replace I mowanice (1 year eyele)	۷,٦٥١

Description	Expenditures
Replacement Year 28-29 continued Pool Pumps & Equipment Allowance	2,437
Pocket Park Components Benches/Trash Cans/Etc Allow (1 year cycle)	1,218
Total for 2028 - 2029	\$42,191
Replacement Year 29-30	
Phase I - Misc.Site Components	
Asphalt Mill & Overlay 1 1/2" - Parking Lot	37,046
Concrete Curb Allowance at Paving	3,122
Concrete Pavers - Parking Lot	23,579
Concrete Sidewalk Repair/Replace Allowance	1,873
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,249
Phase I - Fencing & Gates	
Aluminun Fence 4 ft Pool	43,369
Dumpster Enclosure Gates	2,997
Phase I - Site Lighting	,
Light Poles - Basketball Court	7,493
Light Poles - Parking Lot	8,742
Light Poles - Tennis Court	22,480
Pendent Lights - Bld Patio	6,494
Phase I - Furniture, Fixtures & Equipment	-, -
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,371
Pool Furniture Partial Replace (1 year cycle)	2,498
Phase I - Swimming Pool	_, ., .
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,498
Shade Structures Frame/Fabric	9,991
Phase II - Fencing & Gates	- 7
Aluminun Fence 4 ft Pool	43,369
Phase II - Furniture, Fixtures, Equipment	,.
Pool Furniture Partial Replace (1 year cycle)	2,498
	2,170
Phase II - Swimming Pool Pool Filtration Repair/Replace Allowance (1 year cycle)	2,498
Pool Pumps & Equipment Allowance	2,498
1 0011 umps & Equipment Anowance	4, 4 30

Description	Expenditures
Replacement Year 29-30 continued	
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,249
Picnic Tables - Expanded Metal	2,997
Total for 2029 - 2030	\$232,910
Replacement Year 30-31	
Phase I - Misc.Site Components	
Pond Fountain	2,560
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,280
Phase I - Flooring/Interior Finishes	
Laminated Wood Flooring - Fitness Center	6,508
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,480
Fitness Room TV's	1,536
Office Furniture/Computers	2,816
Pool Furniture Partial Replace (1 year cycle)	2,560
Phase I - Tennis Court	
Rebound Wall/Deck Refurbishment Allowance	2,560
Phase I - Outdoor Fitness Trail	
Outdoor Fitness Equipment (phase 1)	30,722
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,560
Shade Structures Fabric	6,144
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,560
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,560
Pool Pumps & Equipment Allowance	2,560
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,280
Total for 2030 - 2031	\$72,688

Description	Expenditures
Replacement Year 31-32	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	4,325
Monument Sign North - Refurbish Allowance	3,936
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,312
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,592
Golf Cart	9,447
Pool Furniture Partial Replace (1 year cycle)	2,624
Phase I - Mechanical Systems	
Heat Pump - Fitness Center 3 Ton	7,216
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,624
Phase II - Misc Site Components	
Asphalt Seal Coat - Parking Lot	2,204
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,624
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,624
Pool Pumps & Equipment Allowance	2,624
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,312
Total for 2031 - 2032	\$47,466
Replacement Year 32-33	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,345
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,707
Pool Furniture Partial Replace (1 year cycle)	2,690
Phase I - Playground	
Shade Structure Fabric - Playground	8,473
Shade Structure Frame/Fabric - Playground	18,828

Description	Expenditures
Replacement Year 32-33 continued	
Phase I - Tennis Court	
Tennis Court Resurfacing (color coat)	8,559
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,690
Shade Structure Fabric	3,228
Phase II - Misc. Bld Components	
Pool Restrooms Renovation Allowance	26,898
Phase II - Exterior Painting	
Buildings/Pergola	18,748
Phase II - Flooring/Interior Finishes	
Laminate Cabinets & Top - Clubhouse	4,236
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture (Full Replacement)	53,796
Pool Furniture Partial Replace (1 year cycle)	2,690
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,690
Pool Pumps & Equipment Allowance	2,690
Pool Repair/Resurfacing/Tile	97,381
Shade Structures Fabric	6,455
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,345
Total for 2032 - 2033	\$267,447
Replacement Year 33-34	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,379
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,825
Pool Furniture Partial Replace (1 year cycle)	2,757
Phase I - Mechanical Systems	
Heat Pump - Office 1.5 Ton	6,203
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,757

Description	Expenditures
Replacement Year 33-34 continued	
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,757
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,757
Pool Pumps & Equipment Allowance	2,757
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,379
Total for 2033 - 2034	\$27,570
Replacement Year 34-35	
Phase I - Misc.Site Components	
Wood Retaining Wall - Pond	43,669
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,413
Phase I - Roofing	
Standing Seam Metal Roof - Clubhouse	142,905
Phase I - Exterior Painting	10.500
Buildings/Wood Ceilings	19,782
Phase I - Furniture, Fixtures & Equipment	4045
Fitness Equip. Partial Replace Allowance (1 year cycle)	4,945
Pool Furniture Partial Replace (1 year cycle)	2,826
Phase I - Basketball Court Pagketball Court Pagurfaging (color cont)	4,493
Basketball Court Resurfacing (color coat)	4,493
Phase I - Swimming Pool Concrete Pavers - Pool Deck	96,320
Filtration Equipment Refurbish Allowance	42,389
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,826
Phase II - Misc Site Components	
East Monument Sign Refurbish Allowance	2,826
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,826
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,826

Description	Expenditures
Replacement Year 34-35 continued	
Pool Pumps & Equipment Allowance	2,826
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,413
Light Poles	13,847
Picnic Pavilion	11,572
Total for 2034 - 2035	\$399,704
Replacement Year 35-36	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	4,774
Pond Fountain	2,897
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,448
Phase I - Exterior Painting	
Maintenance Building	6,952
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	5,069
Fitness Room TV's	1,738
Office Furniture/Computers	3,186
Pool Furniture Partial Replace (1 year cycle)	2,897
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,897
Phase II - Misc Site Components	
Asphalt Seal Coat - Parking Lot	2,433
Phase II - Flooring/Interior Finishes	
Interior Painting - CH/Restrooms	7,647
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,897
Phase II - Basketball Court	
Basketball Court Resurfacing (color coat)	11,019
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,897
Pool Pumps & Equipment Allowance	2,897

Description	Expenditures
Replacement Year 35-36 continued	
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,448
Total for 2035 - 2036	\$63,094
Replacement Year 36-37	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,485
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	5,196
Pool Furniture Partial Replace (1 year cycle)	2,969
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,969
Phase II - Flooring/Interior Finishes	
Flooring - Clubhouse	9,263
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	2,969
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	2,969
Pool Pumps & Equipment Allowance	2,969
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,485
Total for 2036 - 2037	\$32,273
Replacement Year 37-38	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,522
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	5,326
Pool Furniture Partial Replace (1 year cycle)	3,043
Phase I - Mechanical Systems	
Water Coolers	4,108
Phase I - Tennis Court	
Tennis Court Resurfacing (color coat)	9,684

Description	Expenditures
Replacement Year 37-38 continued	
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,043
Pool Repair/Resurfacing/Tile	144,432
Shade Structure Frame/Fabric	12,173
Phase II - Misc Site Components	
Asphalt Mill & Overlay 1 1/2" - Parking Lot	23,007
Concrete Sidewalk Repair/Replace Allowance	1,522
Phase II - Site Lighting	
Light Poles - Basketball Court	18,259
Light Poles - Parking Lot	10,651
Light Poles - Playgound	22,824
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,043
Phase II - Mechanical Systems	
Water Coolers	4,108
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,043
Pool Pumps & Equipment Allowance	3,043
Shade Structures Frame/Fabric	24,346
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,522
Total for 2037 - 2038	\$298,700
Replacement Year 38-39	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,560
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	5,459
Pool Furniture Partial Replace (1 year cycle)	3,119
Phase I - Tennis Court	
Rebound Wall/Deck Refurbishment Allowance	3,119
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,119

Description	Expenditures
Replacement Year 38-39 continued	
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,119
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,119
Pool Pumps & Equipment Allowance	3,119
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,560
Total for 2038 - 2039	\$27,294
Replacement Year 39-40	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	5,269
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,599
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	5,595
Pool Furniture Partial Replace (1 year cycle)	3,197
Phase I - Playground	62 046
Play Equipment Allowance	63,946
Phase I - Swimming Pool Pool Filtration Repair/Replace Allowance (1 year cycle)	3,197
	3,197
Phase II - Misc Site Components Asphalt Seal Coat - Parking Lot	2,686
Phase II - Furniture, Fixtures, Equipment	2,000
Pool Furniture Partial Replace (1 year cycle)	3,197
Phase II - Swimming Pool	3,197
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,197
Pool Pumps & Equipment Allowance	3,197
Wood Repair/Replace - Pergola	28,136
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,599
Play Equipment Allowance	47,960
Spring Riders	2,558
Total for 2039 - 2040	\$175,334

Description	Expenditures
Replacement Year 40-41	
Phase I - Misc.Site Components	
Pond Fountain	3,277
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,639
Phase I - Furniture, Fixtures & Equipment	
Fitness Equipment Replacement Allowance	45,062
Fitness Room TV's	1,966
Office Furniture/Computers	3,605
Pool Furniture Partial Replace (1 year cycle)	3,277
Phase I - Swimming Pool	2 277
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,277
Shade Structures Fabric	7,865
Phase II - Exterior Painting	22.942
Buildings/Pergola	22,842
Phase II - Furniture, Fixtures, Equipment	2 277
Pool Furniture Partial Replace (1 year cycle)	3,277
Phase II - Swimming Pool	2 277
Pool Filtration Repair/Replace Allowance (1 year cycle) Pool Pumps & Equipment Allowance	3,277 3,277
	3,211
Pocket Park Components Benches/Trash Cans/Etc Allow (1 year cycle)	1,639
Total for 2040 - 2041	\$104,282
Replacement Year 41-42	
Phase I - Misc.Site Components	
Monument Sign North - Refurbish Allowance	5,039
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,680
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	5,879
Pool Furniture Partial Replace (1 year cycle)	3,359
Phase I - Basketball Court	
Basketball Court Resurfacing (color coat)	5,341

Description	Expenditures
Replacement Year 41-42 continued	
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,359
Pool Lift	5,375
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,359
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,359
Pool Pumps & Equipment Allowance	3,359
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,680
Total for 2041 - 2042	\$41,788
Replacement Year 42-43	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,722
Phase I - Exterior Painting	
Buildings/Wood Ceilings	24,102
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,025
Pool Furniture Partial Replace (1 year cycle)	3,443
Phase I - Playground	
Post Swing 2 Bay	6,542
Shade Structure Fabric - Playground	10,846
Phase I - Tennis Court	
Tennis Court Resurfacing (color coat)	10,956
Phase I - Outdoor Fitness Trail	
Renovation Allowance Track Repair/ Surface Replenishment Allowance	3,443
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,443
Shade Structure Fabric	4,132
Phase II - Misc Site Components	
Concrete Curb	5,239
Concrete Pavers	9,641

Description	Expenditures
Replacement Year 42-43 continued	
Exterior Signage	8,608
Phase II - Fencing & Gates	
Vinyl Privacy Fence - Pool Equipment	4,269
Phase II - Roofing	
Standing Seam Metal Roof - CH/Restroom Bld	88,661
Phase II - Flooring/Interior Finishes	
Interior Painting - CH/Restrooms	9,090
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,443
Phase II - Mechanical Systems	
HVAC Systems	20,659
Phase II - Playground	
Climber	5,509
Play Equipment Allowance	51,647
Post Swing One Bay	4,820
Phase II - Basketball Court	
Basketball Court Resurfacing (color coat)	13,098
Basketball Pole & Backboard	5,165
Phase II - Swimming Pool	
Concrete Pavers - Pool Deck	75,763
Filtration Equipment Refurbishment Allowance	51,647
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,443
Pool Lift Pool Pyrone & Equipment Allewance	5,509
Pool Pumps & Equipment Allowance Pool Repair/Resurfacing/Tile	3,443 124,656
Shade Structures Fabric	8,264
Pocket Park Components	0,201
Benches/Trash Cans/Etc Allow (1 year cycle)	1,722
Total for 2042 - 2043	
10tal for 2042 - 2043	\$578,949
Replacement Year 43-44	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	5,816
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,765

Description	Expenditures
Replacement Year 43-44 continued	
Phase I - Roofing	
Standing Seam Metal Roof - Maintenance Bld	19,852
Phase I - Exterior Painting	
Maintenance Building	8,470
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,176
Golf Cart	12,705
Pool Furniture Partial Replace (1 year cycle)	3,529
Phase I - Mechanical Systems	
Heat Pump - Fitness Center 3 Ton	9,705
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,529
Phase II - Misc Site Components	
Asphalt Seal Coat - Parking Lot	2,965
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,529
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,529
Pool Pumps & Equipment Allowance	3,529
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,765
Total for 2043 - 2044	\$86,865
Replacement Year 44-45	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,809
Phase I - Fencing & Gates	
Dumpster Enclosure Gates	4,341
Phase I - Misc. Bld Components	
Pool Restrooms Renovation Allowance	54,262
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,331
Pool Furniture (Full Replacement)	72,349

Description	Expenditures
Replacement Year 44-45 continued Pool Furniture Partial Replace (1 year cycle)	3,617
Phase I - Swimming Pool Pool Filtration Repair/Replace Allowance (1 year cycle) Pool Play Equipment	3,617 61,497
Phase II - Flooring/Interior Finishes Flooring - Clubhouse	11,286
Phase II - Furniture, Fixtures, Equipment	2 (17
Pool Furniture Partial Replace (1 year cycle)	3,617
Phase II - Swimming Pool Pool Filtration Papair/Paplace Allowance (1 year cycle)	2 617
Pool Filtration Repair/Replace Allowance (1 year cycle) Pool Pumps & Equipment Allowance	3,617 3,617
Pocket Park Components	3,017
Benches/Trash Cans/Etc Allow (1 year cycle)	1,809
Picnic Tables - Expanded Metal	4,341
Total for 2044 - 2045	\$236,111
Replacement Year 45-46	
Phase I - Misc.Site Components	
Pond Fountain	3,708
Phase I - Misc. Site Furnishings Benches/Trash Cans/ Etc Allow (1 year cycle)	1,854
Phase I - Misc. Bld Components	
Fitness Restrooms Renovation Allowance	18,539
Phase I - Flooring/Interior Finishes	
Laminated Wood Flooring - Fitness Center	9,425
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,489
Fitness Room TV's	2,225
Office Furniture/Computers	4,079
Pool Furniture Partial Replace (1 year cycle)	3,708
Phase I - Mechanical Systems Heat Pump - Office 1.5 Ton	8,343
Phase I - Basketball Court	
Basketball Pole & Backboard	3,708


Description	Expenditures
Replacement Year 45-46 continued	
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,708
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,708
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,708
Pool Pumps & Equipment Allowance	3,708
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,854
Total for 2045 - 2046	\$78,763
20112 2012 2010	ψ. σ , : σ σ
Replacement Year 46-47	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,900
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,651
Pool Furniture Partial Replace (1 year cycle)	3,801
Phase I - Tennis Court	
Rebound Wall/Deck Refurbishment Allowance	3,801
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,801
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,801
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,801
Pool Pumps & Equipment Allowance	3,801
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,900
Total for 2046 - 2047	\$33,255
	Ψου,200
Replacement Year 47-48	
Phase I - Misc.Site Components	
Asphalt Seal Coat - Parking Lot	6,420

Description	Expenditures
Replacement Year 47-48 continued	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,948
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,817
Pool Furniture Partial Replace (1 year cycle)	3,896
Phase I - Tennis Court	
Tennis Court Resurfacing (color coat)	12,396
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,896
Pool Repair/Resurfacing/Tile	184,885
Phase II - Misc Site Components	
Asphalt Seal Coat - Parking Lot	3,272
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,896
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,896
Pool Pumps & Equipment Allowance	3,896
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,948
Total for 2047 - 2048	\$237,164
Replacement Year 48-49	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	1,996
Phase I - Fencing & Gates	
Chain Link Fence - Tennis Court	15,153
Phase I - Site Lighting	
Light Poles - Pool Deck	7,187
Phase I - Furniture, Fixtures & Equipment	
Fitness Equip. Partial Replace Allowance (1 year cycle)	6,988
Pool Furniture Partial Replace (1 year cycle)	3,993
Phase I - Basketball Court	
Basketball Court Resurfacing (color coat)	6,349

Description	Expenditures
Replacement Year 48-49 continued	
Phase I - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,993
Phase II - Exterior Painting	
Buildings/Pergola	27,831
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	3,993
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	3,993
Pool Pumps & Equipment Allowance	3,993
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	1,996
Total for 2048 - 2049	\$87,466
Replacement Year 49-50	
Phase I - Misc. Site Furnishings	
Benches/Trash Cans/ Etc Allow (1 year cycle)	2,046
Phase I - Site Lighting	2,010
Pendent Lights - Bld Patio	10,641
Phase I - Furniture, Fixtures & Equipment	10,011
Fitness Equip. Partial Replace Allowance (1 year cycle)	7,162
Pool Furniture Partial Replace (1 year cycle)	4,093
Phase I - Mechanical Systems	,
Water Coolers	5,525
Phase I - Swimming Pool	- 7-
Pool Filtration Repair/Replace Allowance (1 year cycle)	4,093
Phase II - Misc Site Components	,
East Monument Sign Refurbish Allowance	4,093
Phase II - Flooring/Interior Finishes	
Interior Painting - CH/Restrooms	10,805
Phase II - Furniture, Fixtures, Equipment	
Pool Furniture Partial Replace (1 year cycle)	4,093
Phase II - Mechanical Systems	
Water Coolers	5,525

Description	Expenditures
Replacement Year 49-50 continued	
Phase II - Basketball Court	
Basketball Court Resurfacing (color coat)	15,569
Phase II - Swimming Pool	
Pool Filtration Repair/Replace Allowance (1 year cycle)	4,093
Pool Pumps & Equipment Allowance	4,093
Pocket Park Components	
Benches/Trash Cans/Etc Allow (1 year cycle)	2,046
Total for 2049 - 2050	\$83,878

Brandy Creek CDD Update 2020/2021 Asset Current Cost by Category



Component Condition Assessment

Misc. Site Components

- Various monument signs are located in the District that appear in good condition.
- Street signs and poles should be cleaned and painted upon inspection.
- Wood bulkhead and pier appear good condition from visual inspection of above waterline areas.

Parking Lot/Streets

- Asphalt is in good condition for its age with some damage at catch basis.
- Seal coating is included after the asphalt resurfacing.

Fencing & Gates

- Fencing, gates, railings appear in good condition. Dumpster gates show some wear due to their use.
- Tennis court fencing requires some immediate cleaning and repair.

Stormwater System

• Pond fountains do not have a predictable useful life therefore an allowance of one replacement per 4-year cycle is included. Pump and motor size unknown.

Site Lighting

• District has variety of site lighting that appears in good condition. Site visit was conducted during daytime hours, so performance of lights is unknown.

Misc. Building Components

- Restroom refurbishment allowance is included to allow flexibility for material selection determined at the time of replacement.
- We find vinyl ceilings located in exterior locations tends to deform over time.
- Wood cabinets and top are like new.
- Wood decking at covered porch is like new.

Roofing

- Asphalt shingles have been installed on the new section of the clubhouse and do not match the existing. At the time of replacement of the original roof this area is included. Shingle areas should be inspected annually, and repairs completed.
- Metal roofing appears in good condition and should be inspected annually, and repairs completed.

Exterior Painting

• Exterior walls should be properly prepared prior to painting with all material joints sealed, window and door connections to siding sealed.

FF&E

- Access control system appear to operate correctly. Replacement of controls is included.
- Fitness equipment does not have a predictable life therefore regular replacement is assumed funded by the operating budget with a full replacement allowance included in this analysis.
- Furniture allowances for interior and exterior spaces in included.
- Site furniture includes benches and tables appear in good condition.
- Kitchen appliances generally have a useful life of 12 years with regular use. In the location of this type that life is extended.
- Shade structures at pool should not need replacement with regular repair. Immediate repair and painting are needed.
- Shade fabric is near end of its useful life.

HVAC

• Clubhouse has two heat pumps that we assume are original equipment. Generally, this component has a 12-year life. Annual inspection and cleaning of units is recommended.

Swimming Pool

- Concrete pool deck pavers appear structurally sound, but we find over time the aggregate begins to appear due to wear and do not provide the level of quality the District will expect.
- An allowance for major filtration refurbishment is included for pumps, motors and other equipment.
- Pool lift appears in good condition but was not operated. The life should remain covered until needed to prevent exposure to the elements.
- Pool was resurfaced in 2019 and in good condition.

Tennis Court

• Tennis court resurfacing is included on a 7-year cycle.

Playground

• Play equipment and swings appear in good condition. An inspection is recommended annually with needed repairs completed.

	٠.٥	چ <u>ر</u> ف	gent Self	<u> </u>	iggerit .	igra		*
Description	On Sol	565 76	is Jell	y dij	Solig	Sitts	उत्ता ८०%	CHECOS
Phase I - Misc.Site Components								
Asphalt Mill & Overlay 1 1/2" - Parking L		29-30	25	0	9	1,648 SY	18.00	29,664
Asphalt Seal Coat - Parking Lot Concrete Curb Allowance at Paving	2019 2005	23-24 29-30	4 25	1 0	3 9	1,648 SY 1 LS	2.00 2,500.00	3,296 2,500
Concrete Pavers - Parking Lot	2005	29-30	25	0	9	2,360 SF	8.00	18,880
Concrete Sidewalk Repair/Replace Allowa	2005	29-30	25	0	9	1 LS	1,500.00	1,500
Monument Sign North - Refurbish Allowa	2005	21-22	10	7	1	1 LS	3,000.00	3,000
Pond Fountain	2014	20-21	5	0	0	1 LS	2,000.00	2,000
Wood Retaining Wall - Pond	2005	34-35	30	0	14	303 LF	102.00	30,906
Phase I - Misc.Site Components - Total								\$91,746
Phase I - Misc. Site Furnishings								
Benches/Trash Cans/ Etc Allow (1 year cy	2020	21-22	1	1	1	1 LS	1,000.00	1,000
Phase I - Misc. Site Furnishings - Total								\$1,000
Phase I - Fencing & Gates								
Aluminun Fence 4 ft Pool	2005	29-30	25	0	9	847 LF	41.00	34,727
Chain Link Fence - Tennis Court	2005 2015	26-27 29-30	22 15	0	6 9	345 LF 2 EA	22.00 1,200.00	7,590
Dumpster Enclosure Gates Phase I - Fencing & Gates - Total	2013	29-30	13	U	9	2 EA	1,200.00	\$44,717
Dhaga I Sita Lighting								
Phase I - Site Lighting Light Poles - Basketball Court	2005	29-30	25	0	9	2 EA	3,000.00	6,000
Light Poles - Parking Lot	2005	29-30	25	0	9	2 EA 2 EA	3,500.00	7,000
Light Poles - Pool Deck	2005	26-27	22	0	6	2 EA	1,800.00	3,600
Light Poles - Tennis Court	2005	29-30	25	0	9	6 EA	3,000.00	18,000
Pendent Lights - Bld Patio	2005	29-30	20	5	9	13 EA	400.00	5,200
Phase I - Site Lighting - Total								\$39,800
Phase I - Misc. Bld Components								
Fitness Restrooms Renovation Allowance	2005	25-26	20	1	5	1 LS	10,000.00	10,000
Pool Restrooms Renovation Allowance	2005	24-25	20	0	4	2 EA	15,000.00	30,000
Phase I - Misc. Bld Components - Total								\$40,000
Phase I - Roofing								
Standing Seam Metal Roof - Clubhouse	2005	34-35	30	0	14	8,091 SF	12.50	101,137
Standing Seam Metal Roof - Maintenance Phase I - Roofing - Total	2014	43-44	30	0	23	900 SF	12.50	11,250 \$112,387
Phase I - Exterior Painting								
Buildings/Wood Ceilings	2019	26-27	8	0	6	1 LS	14,000.00	14,000
Maintenance Building	2014	27-28	8	6	7	2,400 SF	2.00	4,800
Phase I - Exterior Painting - Total								\$18,800

		1	geril .		ent	. 🕬					
	Operation of	ي م	gan Jesti	> **		Signit Signit	* *	CHICOS			
Description	ځ _ه	\$6,76	5 5	₽.	₹ [©]	SW	المالة	0,0			
Phase I - Flooring/Interior Finishes											
Laminated Wood Flooring - Fitness Center	2016	30-31	15	0	10	820 SF	6.20	_5,084			
Phase I - Flooring/Interior Finishes - Total	al							\$5,084			
Phase I - Furniture, Fixtures & Equipment											
Fitness Equip. Partial Replace Allowance (20-21	1	0	0	1 LS	3,500.00	3,500			
Fitness Equipment Replacement Allowance	2016	40-41	25	0	20	1 LS	27,500.00	27,500			
Fitness Room TV's	2014	20-21	5	0	0	2 EA	600.00	1,200			
Golf Cart	2020	31-32	12	0	11	1 EA	7,200.00	7,200			
Office Furniture/Computers	2020	25-26	5	1	5	1 LS	2,200.00	2,200			
Pool Furniture (Full Replacement)	2005	24-25	20	0	4	1 LS	40,000.00	40,000			
Pool Furniture Partial Replace (1 year cycl		20-21	1	0	0	1 LS	2,000.00	2,000			
Phase I - Furniture, Fixtures & Equipmen	nt - Total							\$83,600			
Phase I - Mechanical Systems											
Heat Pump - Fitness Center 3 Ton	2020	31-32	12	0	11	1 EA	5,500.00	5,500			
Heat Pump - Office 1.5 Ton	2005	21-22	12	5	1	1 EA	4,500.00	4,500			
Water Coolers	2005	25-26	12	9	5	3 EA	900.00	2,700			
Phase I - Mechanical Systems - Total								\$12,700			
Phase I - Playground											
Play Equipment Allowance	2005	24-25	15	5	4	1 LS	40,000.00	40,000			
Post Swing 2 Bay	2013	27-28	15	0	7	1 EA	3,800.00	3,800			
Shade Structure Fabric - Playground	2013	22-23	10	0	2	1 LS	6,300.00	6,300			
Shade Structure Frame/Fabric - Playground	2013	32-33	20	0	12	1 LS	14,000.00	14,000			
Phase I - Playground - Total							,	\$64,100			
Phase I - Tennis Court											
Rebound Wall/Deck Refurbishment Allow	2013	22-23	8	2	2	1 LS	2,000.00	2,000			
Tennis Court Resurfacing (color coat)	2016	22-23	5	2	2	740 SY	8.60	_6,364			
Phase I - Tennis Court - Total								\$8,364			
Phase I - Outdoor Fitness Trail											
Outdoor Fitness Equipment (phase 1)	2013	25-26	13	0	5	1 EA	4,000.00	4,000			
Outdoor Fitness Equipment (phase 1)	2013	30-31	18	0	10	6 EA	4,000.00	24,000			
Renovation Allowance Track Repair/ Surf	2013	27-28	15	0	7	1 LS	2,000.00	2,000			
Phase I - Outdoor Fitness Trail - Total								\$30,000			
Phase I - Basketball Court											
Basketball Court Resurfacing (color coat)	2010	20-21	7	0	0	265 SY	12.00	3,180			
Basketball Pole & Backboard	2005	25-26	20	1	5	1 EA	2,000.00	2,000			
Phase I - Basketball Court - Total		-	-		-		,	\$5,180			
								. ,			

		ć	gent.		est.	. o [©] o		
	Spirit is	\$ \$\frac{1}{2}\frac{1}	, \$ _Si	> '**	Portion of the second	Jaks	عَظَّ وَحَدُّ عَلَيْهِ مِنْ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ عَلَيْهِ ع	
Description	ئي جي	\$6,76	5	Ø,	&	25	\$ 6	8 8
Phase I - Swimming Pool								
Concrete Pavers - Pool Deck	2005	34-35	30	0	14	8,521 SF	8.00	68,168
Filtration Equipment Refurbish Allowance	2005	34-35	30	0	14	1 LS	30,000.00	30,000
Pool Filtration Repair/Replace Allowance	2005	20-21	1	0	0	1 LS	2,000.00	2,000
Pool Lift	2012	26-27	15	0	6	1 EA	3,200.00	3,200
Pool Play Equipment	2005	24-25	20	0	4	1 LS	34,000.00	34,000
Pool Repair/Resurfacing/Tile	2018	27-28	10	0	7	6,780 SF	14.00	94,920
Shade Structure Fabric	2013	22-23	10	0	2	2 EA	1,200.00	2,400
Shade Structure Frame/Fabric	2013	37-38	25	0	17	2 EA	4,000.00	8,000
Shade Structures Fabric	2005	20-21	10	0	0	4 EA	1,200.00	4,800
Shade Structures Frame/Fabric	2005	29-30	25	0	9	2 EA	4,000.00	8,000
Phase I - Swimming Pool - Total								\$255,488
Phase II - Misc Site Components								
Asphalt Mill & Overlay 1 1/2" - Parking L	2013	37-38	25	0	17	840 SY	18.00	15,120
Asphalt Seal Coat - Parking Lot	2019	23-24	4	1	3	840 SY	2.00	1,680
Concrete Curb	2013	27-28	15	0	7	340 LF	8.95	3,043
Concrete Pavers	2013	42-43	30	0	22	700 SF	8.00	5,600
Concrete Sidewalk Repair/Replace Allowa	2013	37-38	25	0	17	1 LS	1,000.00	1,000
East Monument Sign Refurbish Allowance	2020	34-35	15	0	14	1 LS	2,000.00	2,000
Exterior Signage	2013	27-28	15	0	7	1 LS	5,000.00	5,000
Phase II - Misc Site Components - Total		_, _,			·		2,000.00	\$33,443
Phase II - Fencing & Gates					_			
Aluminun Fence 4 ft Pool	2005	29-30	25	0	9	847 LF	41.00	34,727
Vinyl Privacy Fence - Pool Equipment	2013	42-43	30	0	22	80 LF	31.00	2,480
Phase II - Fencing & Gates - Total								\$37,207
Phase II - Site Lighting								
Light Poles - Basketball Court	2013	37-38	25	0	17	4 EA	3,000.00	12,000
Light Poles - Parking Lot	2013	37-38	25	0	17	2 EA	3,500.00	7,000
Light Poles - Playgound	2013	37-38	25	0	17	5 EA	3,000.00	_15,000
Phase II - Site Lighting - Total							,	\$34,000
Dhaga II Miga Did Cammananta								
Phase II - Misc. Bld Components	2012	22.22	20	0	10	2.54	10,000,00	20,000
Pool Restrooms Renovation Allowance	2013	32-33	20	0	12	2 EA	10,000.00	20,000 \$20,000
Phase II - Misc. Bld Components - Total								\$20,000
Phase II - Roofing								
Standing Seam Metal Roof - CH/Restroom	2013	42-43	30	0	22	4,120 SF	12.50	_51,500
Phase II - Roofing - Total								\$51,500
Phase II - Exterior Painting								
Buildings/Pergola	2017	24-25	8	0	4	3,400 SF	4.10	_13,940
Phase II - Exterior Painting - Total	2017	Z 4 -ZJ	o	U	4	3,400 BF	4.10	\$13,940
Thase II - Exterior Familing - Total								\$13,940

			gent.		ent	. &º		
-	Oge Sta		gent Seli	} ;	Star Sag	Salis Salis	عرفة ومع	CHE CHE
Description	ځي جي	&0,√6	5 5	Ø,	\$€	\$	\$ 50	000
Phase II - Flooring/Interior Finishe								
Flooring - Clubhouse	2013	20-21	8	0	0	1,040 SF	6.00	6,240
Interior Painting - CH/Restrooms	2013	21-22	7	2	1	1 LS	5,280.00	5,280
Laminate Cabinets & Top - Clubhouse	2013	32-33	20	0	12	14 LF	225.00	3,150 \$14,670
Phase II - Flooring/Interior Finishes - To	tai							\$14,670
Phase II - Furniture, Fixtures, Equi	ipment							
Pool Furniture (Full Replacement)	2013	32-33	20	0	12	1 LS	40,000.00	40,000
Pool Furniture Partial Replace (1 year cycl	2013	20-21	1	0	0	1 LS	2,000.00	
Phase II - Furniture, Fixtures, Equipmen	t - Total							\$42,000
Phase II - Mechanical Systems								
HVAC Systems	2013	27-28	15	0	7	8 TONS	1,500.00	12,000
Water Coolers	2013	25-26	12	1	5	3 EA	900.00	2,700
Phase II - Mechanical Systems - Total								\$14,700
Phase II - Playground	•				_		• • • • • • •	
Climber	2013	27-28	15	0	7	1 EA	3,200.00	3,200
Play Equipment Allowance Post Swing One Bay	2013 2013	27-28 27-28	15 15	0	7 7	1 LS 1 LS	30,000.00 2,800.00	30,000 2,800
Phase II - Playground - Total	2013	21-20	13	U	,	1 LS	2,000.00	\$36,000
Thase IT Thayground Total								Ψ30,000
Phase II - Basketball Court								
Basketball Court Resurfacing (color coat)	2013	21-22	7	2	1	634 SY	12.00	7,608
Basketball Pole & Backboard	2013	27-28	15	0	7	2 EA	1,500.00	3,000
Phase II - Basketball Court - Total								\$10,608
Phase II - Swimming Pool								
Concrete Pavers - Pool Deck	2013	42-43	30	0	22	5,501 SF	8.00	44,008
Filtration Equipment Refurbishment Allo	2013	42-43	30	0	22	1 LS	30,000.00	30,000
Pergola Repair Allowance	2013	20-21	1	0	0	1 Lump Sum	15,000.00	15,000
Pool Filtration Repair/Replace Allowance	2005	20-21	1	0	0	1 LS	2,000.00	2,000
Pool Lift	2013	27-28	15	0	7	1 EA	3,200.00	3,200
Pool Pumps & Equipment Allowance Pool Repair/Resurfacing/Tile	2013 2013	20-21 22-23	1 10	0	0	1 LS 5,172 SF	2,000.00 14.00	2,000
Shade Structures Fabric	2013	22-23	10	0	2 2	3,172 SF 4 EA	1,200.00	72,408 4,800
Shade Structures Frame/Fabric	2013	37-38	25	0	17	4 EA	4,000.00	16,000
Wood Repair/Replace - Pergola	2020	39-40	20	0	19	800 SF	22.00	17,600
Phase II - Swimming Pool - Total								\$207,016
Pocket Park Components								
Benches/Trash Cans/Etc Allow (1 year cyc	2020	21-22	1	1	1	1 LS	1,000.00	1,000
Light Poles	2010	34-35	25	0	14	7 EA	1,400.00	9,800
Picnic Pavilion	2010	34-35	25	0	14	273 SF	30.00	8,190
Picnic Tables - Expanded Metal	2010	29-30	15	5	9	2 EA	1,200.00	2,400

	·\$:	ల త్ర	geni	> 2	Qedaiding	9		ă
Description	One ser	\$ \$3\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	ist Jest	A Silly	Sedig	Jaks	Jill Cost	رغايل رفخ
Pocket Park Components continued								
Play Equipment Allowance	2010	24-25	15	0	4	1 LS	30,000.00	30,000
Spring Riders	2010	24-25	15	0	4	2 EA	800.00	1,600
Pocket Park Components - Total								\$52,990

Components Not Included

Components Not Included - Total

Components Not included	
Access Control Systen	Unfunded
Access Control Systen	Unfunded
Aluminum Flag Poles	Unfunded
Audio Equipment	Unfunded
Exterior Decorative Louvers	Unfunded
Exterior Doors	Unfunded
Exterior Fireplace & Chimney	Unfunded
Exterior Siding/Trim	Unfunded
Exterior Signage	Unfunded
Fitness Room Ceiling Fans	Unfunded
Gutters/Downspouts	Unfunded
Interior Painting - Clubhouse/Restrooms	Unfunded
Office Carpet & Paint Renovation	Unfunded
Patio Bar/Sink Phase 1	Unfunded
Pool Hand Rails	Unfunded
Pool Shower Poles	Unfunded
Storm Water Pond Maintenance	Unfunded
Street Signs	Unfunded
Tennis Court Net Replacement	Unfunded
Tennis Court Replacement	Unfunded
Water Heater	Unfunded
Windows	Unfunded

Total Asset Summary \$1,381,040

Phase I - Misc.Site Components 1036 Asphalt Mill & Overlay 1 1/2" - Parking Lot 29-30 5-13 1037 Asphalt Seal Coat - Parking Lot 23-24 5-14 1045 Concrete Curb Allowance at Paving 29-30 5-15 1039 Concrete Pavers - Parking Lot 29-30 5-15 1043 Concrete Sidewalk Repair/Replace Allowance 29-30 5-16 1040 Monument Sign North - Refurbish Allowance 21-22 5-16 1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings 1053 Benches/Trash Cans/ Etc Allow (1 year cycle) 21-22 5-19				
1036 Asphalt Mill & Overlay 1 1/2" - Parking Lot 29-30 5-13 1037 Asphalt Seal Coat - Parking Lot 23-24 5-14 1045 Concrete Curb Allowance at Paving 29-30 5-15 1039 Concrete Pavers - Parking Lot 29-30 5-15 1043 Concrete Sidewalk Repair/Replace Allowance 29-30 5-16 1040 Monument Sign North - Refurbish Allowance 21-22 5-16 1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
1037 Asphalt Seal Coat - Parking Lot 23-24 5-14 1045 Concrete Curb Allowance at Paving 29-30 5-15 1039 Concrete Pavers - Parking Lot 29-30 5-15 1043 Concrete Sidewalk Repair/Replace Allowance 29-30 5-16 1040 Monument Sign North - Refurbish Allowance 21-22 5-16 1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
1045 Concrete Curb Allowance at Paving 29-30 5-15 1039 Concrete Pavers - Parking Lot 29-30 5-15 1043 Concrete Sidewalk Repair/Replace Allowance 29-30 5-16 1040 Monument Sign North - Refurbish Allowance 21-22 5-16 1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
1039 Concrete Pavers - Parking Lot 29-30 5-15 1043 Concrete Sidewalk Repair/Replace Allowance 29-30 5-16 1040 Monument Sign North - Refurbish Allowance 21-22 5-16 1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
1043Concrete Sidewalk Repair/Replace Allowance29-305-161040Monument Sign North - Refurbish Allowance21-225-161044Pond Fountain20-215-171038Wood Retaining Wall - Pond34-355-18Phase I - Misc. Site Furnishings				
1040 Monument Sign North - Refurbish Allowance 21-22 5-16 1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
1044 Pond Fountain 20-21 5-17 1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
1038 Wood Retaining Wall - Pond 34-35 5-18 Phase I - Misc. Site Furnishings				
<u>e</u>				
<u>e</u>				
1055 Deliches/ Hash Cans/ Etc Allow (1 year cycle) 21-22 5-19				
Phase I - Fencing & Gates				
1018 Aluminun Fence 4 ft Pool 29-30 5-20				
1016 Chain Link Fence - Tennis Court 26-27 5-20				
1017 Dumpster Enclosure Gates 29-30 5-22				
Phase I - Site Lighting				
1035 Light Poles - Basketball Court 29-30 5-23				
1032 Light Poles - Parking Lot 29-30 5-24				
1030 Light Poles - Pool Deck 26-27 5-25				
1034 Light Poles - Tennis Court 29-30 5-26				
1031 Pendent Lights - Bld Patio 29-30 5-27				
Phase I - Misc. Bld Components				
1014 Fitness Restrooms Renovation Allowance 25-26 5-28				
1012 Pool Restrooms Renovation Allowance 24-25 5-28				
Phase I - Roofing				
1077 Standing Seam Metal Roof - Clubhouse 34-35 5-30				
1076 Standing Seam Metal Roof - Maintenance Bld 43-44 5-30				
Phase I - Exterior Painting				
1002 Buildings/Wood Ceilings 26-27 5-32				
1003 Maintenance Building 27-28 5-33				
Phase I - Flooring/Interior Finishes				
1078 Laminated Wood Flooring - Fitness Center 30-31 5-34				

Asset IDDescription		Replacement	Page
Phase 1	I - Furniture, Fixtures & Equipment		
1007	Fitness Equip. Partial Replace Allowance (1 year cyc.	. 20-21	5-35
1131	Fitness Equipment Replacement Allowance	40-41	5-35
1008	Fitness Room TV's	20-21	5-36
1128	Golf Cart	31-32	5-37
1005	Office Furniture/Computers	25-26	5-38
1101	Pool Furniture (Full Replacement)	24-25	5-39
1004	Pool Furniture Partial Replace (1 year cycle)	20-21	5-40
Dhaga l	I - Mechanical Systems		
1048	Heat Pump - Fitness Center 3 Ton	31-32	5-41
1043	Heat Pump - Office 1.5 Ton	21-22	5-41 5-42
1047	Water Coolers	25-26	5-42 5-43
1040	water Coolers	23-20	J -4 3
Phase 1	I - Playground		
1052	Play Equipment Allowance	24-25	5-44
1055	Post Swing 2 Bay	27-28	5-45
1054	Shade Structure Fabric - Playground	22-23	5-46
1056	Shade Structure Frame/Fabric - Playground	32-33	5-47
Phase 1	I - Tennis Court		
1058	Rebound Wall/Deck Refurbishment Allowance	22-23	5-48
1057	Tennis Court Resurfacing (color coat)	22-23	5-49
1057	Termin Court Resultating (color coat)	22 23	5 17
Phase 1	I - Outdoor Fitness Trail		
1051	Outdoor Fitness Equipment (phase 1)	25-26	5-50
1049	Outdoor Fitness Equipment (phase 1)	30-31	5-51
1050	Renovation Allowance Track Repair/ Surface Reple	27-28	5-52
Phase 1	I - Basketball Court		
1059	Basketball Court Resurfacing (color coat)	20-21	5-53
1060	Basketball Pole & Backboard	25-26	5-54
1000	Bushetoun I ole & Buckeourd	20 20	00.
Phase 1	I - Swimming Pool		
1020	Concrete Pavers - Pool Deck	34-35	5-55
1023	Filtration Equipment Refurbish Allowance	34-35	5-55
1021	Pool Filtration Repair/Replace Allowance (1 year cy	20-21	5-57
1027	Pool Lift	26-27	5-57

Asset IDDescription		Replacement	Page		
Phase I - Swimming Pool Continued					
1019	Pool Play Equipment	24-25	5-59		
1022	Pool Repair/Resurfacing/Tile	27-28	5-59		
1025	Shade Structure Fabric	22-23	5-60		
1028	Shade Structure Frame/Fabric	37-38	5-60		
1024	Shade Structures Fabric	20-21	5-61		
1026	Shade Structures Frame/Fabric	29-30	5-62		
Phase 1	II - Misc Site Components				
1085	Asphalt Mill & Overlay 1 1/2" - Parking Lot	37-38	5-63		
1084	Asphalt Seal Coat - Parking Lot	23-24	5-64		
1082	Concrete Curb	27-28	5-65		
1122	Concrete Pavers	42-43	5-66		
1081	Concrete Sidewalk Repair/Replace Allowance	37-38	5-67		
1083	East Monument Sign Refurbish Allowance	34-35	5-68		
1080	Exterior Signage	27-28	5-69		
Phase 1	II - Fencing & Gates				
1086	Aluminun Fence 4 ft Pool	29-30	5-70		
1087	Vinyl Privacy Fence - Pool Equipment	42-43	5-70		
Phase 1	II - Site Lighting				
1090	Light Poles - Basketball Court	37-38	5-71		
1089	Light Poles - Parking Lot	37-38	5-72		
1088	Light Poles - Playgound	37-38	5-73		
Phase 1	II - Misc. Bld Components				
1093	Pool Restrooms Renovation Allowance	32-33	5-74		
Phase II - Roofing					
1094	Standing Seam Metal Roof - CH/Restroom Bld	42-43	5-75		
Phase 1	Phase II - Exterior Painting				
1095	Buildings/Pergola	24-25	5-76		
Phase 1	II - Flooring/Interior Finishes				
1097	Flooring - Clubhouse	20-21	5-77		
1130	Interior Painting - CH/Restrooms	21-22	5-77		
	<i>Q</i>				

Asset IDDescription		Replacement	Page		
Phase II - Flooring/Interior Finishes Continued					
1096	Laminate Cabinets & Top - Clubhouse	32-33	5-78		
Phase 1	II - Furniture, Fixtures, Equipment				
1117	Pool Furniture (Full Replacement)	32-33	5-79		
1100	Pool Furniture Partial Replace (1 year cycle)	20-21	5-80		
Phase 1	II - Mechanical Systems				
1099	HVAC Systems	27-28	5-81		
1098	Water Coolers	25-26	5-82		
Phase 1	II - Playground				
1120	Climber	27-28	5-83		
1106	Play Equipment Allowance	27-28	5-84		
1118	Post Swing One Bay	27-28	5-85		
Phase 1	I - Basketball Court				
1105	Basketball Court Resurfacing (color coat)	21-22	5-86		
1104	Basketball Pole & Backboard	27-28	5-87		
Phase l	II - Swimming Pool				
1115	Concrete Pavers - Pool Deck	42-43	5-88		
1110	Filtration Equipment Refurbishment Allowance	42-43	5-88		
1129	Pergola Repair Allowance	20-21	5-89		
1133	Pool Filtration Repair/Replace Allowance (1 year cy		5-90		
1114	Pool Lift	27-28	5-90		
1116	Pool Pumps & Equipment Allowance	20-21	5-92		
1113	Pool Repair/Resurfacing/Tile	22-23	5-93		
1112	Shade Structures Fabric	22-23	5-94		
1111	Shade Structures Frame/Fabric	37-38	5-95		
1029	Wood Repair/Replace - Pergola	39-40	5-96		
Pocket	Park Components				
1109	Benches/Trash Cans/Etc Allow (1 year cycle)	21-22	5-97		
1126	Light Poles	34-35	5-98		
1108	Picnic Pavilion	34-35	5-99		
1127	Picnic Tables - Expanded Metal	29-30	5-100		
1107	Play Equipment Allowance	24-25	5-101		

Asset IDDescription		Replacement	Page
Pocket	Park Components Continued		
1125	Spring Riders	24-25	5-101
Compo	onents Not Included		
1006	Access Control Systen	Unfunded	5-102
1102	Access Control Systen	Unfunded	5-103
1041	Aluminum Flag Poles	Unfunded	5-104
1011	Audio Equipment	Unfunded	5-105
1064	Exterior Decorative Louvers	Unfunded	5-106
1091	Exterior Doors	Unfunded	5-107
1061	Exterior Fireplace & Chimney	Unfunded	5-108
1071	Exterior Siding/Trim	Unfunded	5-109
1042	Exterior Signage	Unfunded	5-110
1067	Fitness Room Ceiling Fans	Unfunded	5-111
1092	Gutters/Downspouts	Unfunded	5-112
1079	Interior Painting - Clubhouse/Restrooms	Unfunded	5-113
1075	Office Carpet & Paint Renovation	Unfunded	5-114
1063	Patio Bar/Sink Phase 1	Unfunded	5-115
1074	Pool Hand Rails	Unfunded	5-116
1073	Pool Shower Poles	Unfunded	5-117
1072	Storm Water Pond Maintenance	Unfunded	5-118
1132	Street Signs	Unfunded	5-119
1068	Tennis Court Net Replacement	Unfunded	5-120
1070	Tennis Court Replacement	Unfunded	5-121
1062	Water Heater	Unfunded	5-122
1065	Windows	Unfunded	5-123
	Total Funded Assets	98	
	Total Unfunded Assets	_22	
	Total Assets	120	

Asphalt Mill & Overlay 1 1/2" - Parking Lot - 2029

Asset ID	1036 Phase I	1,648 SY Asset Actual Cost Percent Replacement	@ \$18.00 \$29,664.00 100%
Chago ty Mi	sc.Site Components	Future Cost	\$37,046.27
Placed in Service	February 2005		
Useful Life	25		
Replacement Year	29-30		
Remaining Life	9		



Asphalt Seal Coat -	Parking Lot - 2023	1,648 SY	@ \$2.00
Asset ID	1037	Asset Actual Cost	\$3,296.00
	Phase I	Percent Replacement	100%
Character Character Ty-	Misc.Site Components	Future Cost	\$3,549.43
Placed in Service	January 2019		
Useful Life	4		
Adjustment	1		
Replacement Year	23-24		
Remaining Life	3		



1 LS

@ \$2,500.00

\$2,500.00

\$3,122.16

100%

Concrete Curb Allowance at Paving - 2029

Asset ID 1045 Asset Actual Cost Phase I Percent Replacement Chagoly Misc.Site Components **Future Cost** Placed in Service February 2005 Useful Life 25 Replacement Year 29-30 Remaining Life 9



Replacement allowance for broken or damaged curbing.

Concrete Pavers - Parking Lot - 2029

Remaining Life

2,360 SF @ \$8.00 Asset ID 1039 Asset Actual Cost \$18,880.00 Phase I Percent Replacement 100% Characty Misc.Site Components **Future Cost** \$23,578.53 Placed in Service February 2005 Useful Life 25 Replacement Year 29-30



Concrete Sidewalk Repair/Replace Allowance - 2029

Asset ID	1043 Phase I	1 LS Asset Actual Cost Percent Replacement	@ \$1,500.00 \$1,500.00 100%
Chago ty- N	Misc.Site Components	Future Cost	\$1,873.29
Placed in Service	February 2005		
Useful Life	25		
Replacement Year	29-30		
Remaining Life	9		



Allowance for future repair

Monument Sign North - Refurbish Allowance - 2021

Asset ID	1040 Phase I	1 LS Asset Actual Cost Percent Replacement	@ \$3,000.00 \$3,000.00 100%
Patte secty	Misc.Site Components	Future Cost	\$3,075.00
Placed in Service	February 2005		
Useful Life	10		
Adjustment	7		
Replacement Year	21-22		
Remaining Life	1		

Monument Sign North - Refurbish Allowance continued...



Pond Fountain - 2020

1 LS @ \$2,000.00 Asset Actual Cost \$2,000.00 Asset ID 1044 Percent Replacement Phase I 100% Chago by Misc. Site Components \$2,000.00 **Future Cost** Placed in Service March 2014 Useful Life 5 Replacement Year 20-21 Remaining Life 0



Wood Retaining Wall - Pond - 2034

303 LF @ \$102.00 \$30,906.00 Asset ID 1038 Asset Actual Cost 100% Phase I Percent Replacement Chasoly Misc.Site Components Future Cost \$43,669.37 Placed in Service February 2005 Useful Life 30 Replacement Year 34-35 Remaining Life 14



187 ft 6-8 Ft high 116 ft 3 ft high

Benches/Trash Cans/ Etc Allow (1 year cycle) - 2021

Asset ID	1053 Phase I	1 LS Asset Actual Cost Percent Replacement	@ \$1,000.00 \$1,000.00 100%
Chargorly- Misc. Site Furnishings		Future Cost	\$1,025.00
Placed in Service	January 2020		
Useful Life	1		
Adjustment	1		
Replacement Year	21-22		
Remaining Life	1		





@ \$41.00

\$34,727.00 100% \$43,369.26

847 LF

Aluminun Fence 4 ft. - Pool - 2029

Asset ID	1018	Asset Actual Cost
	Phase I	Percent Replacement
CategoPhase	e I - Fencing & Gates	Future Cost
Placed in Service	February 2005	
Useful Life	25	
Replacement Year	29-30	
Remaining Life	9	



Aluminum fence 4 Ft high encloses the pool area. In some locations the fence is attached to the top plate of the wood retaining wall and it may be more cost effective to replace the wood structure when the fence is replaced.

Chain Link Fence - Tenr	nis Court - 2026	345 LF	@ \$22.00
Asset ID	1016	Asset Actual Cost	\$7,590.00
	Phase I	Percent Replacement	100%
Categorhase I - Fencing & Gates		Future Cost	\$8,802.07
Placed in Service	February 2005		
Useful Life	22		
Replacement Year	26-27		
Remaining Life	6		

Chain Link Fence - Tennis Court continued...



Dumpster Enclosure Gates - 2029

mpster Enclosure Gates - 2029		2 EA @ \$1,200	
Asset ID	1017	Asset Actual Cost	\$2,400.00
	Phase I	Percent Replacement	100%
Catego Phase I - Fencing & Gates		Future Cost	\$2,997.27
Placed in Service	February 2015		
Useful Life	15		
Replacement Year	29-30		
Remaining Life	9		



Gate replacement may be required using this allowance.

Light Poles - Basketball Court - 2029

2 EA @ \$3,000.00 \$6,000.00 Asset ID 1035 Asset Actual Cost 100% Phase I Percent Replacement Category Phase I - Site Lighting Future Cost \$7,493.18 Placed in Service February 2005 Useful Life 25 29-30 Replacement Year Remaining Life 9



Light Poles - Parking Lot - 2029

ght Poles - Parking Lot - 2029		2 EA	@ \$3,500.00
Asset ID	1032	Asset Actual Cost	\$7,000.00
	Phase I	Percent Replacement	100%
Category	Phase I - Site Lighting	Future Cost	\$8,742.04
Placed in Service	February 2005		
Useful Life	25		
Replacement Year	29-30		
Remaining Life	9		



Light Poles - Pool Deck - 2026

ght Poles - Pool D	eck - 2026	2 EA	@ \$1,800.00
Asset ID	1030	Asset Actual Cost	\$3,600.00
	Phase I	Percent Replacement	100%
Category	Phase I - Site Lighting	Future Cost	\$4,174.90
Placed in Service	February 2005		
Useful Life	22		
Replacement Year	26-27		
Remaining Life	6		



Light Poles - Tennis Court - 2029

ght Poles - Tennis	Court - 2029	6 EA	@ \$3,000.00
Asset ID	1034	Asset Actual Cost	\$18,000.00
	Phase I	Percent Replacement	100%
Category	Phase I - Site Lighting	Future Cost	\$22,479.53
Placed in Service	February 2005		
Useful Life	25		
Replacement Year	29-30		
Remaining Life	9		



Pendent Lights - Bld Patio - 2029

endent Lights - Bld Patio - 2029		13 EA	@ \$400.00
Asset ID	1031	Asset Actual Cost	\$5,200.00
	Phase I	Percent Replacement	100%
Category	Phase I - Site Lighting	Future Cost	\$6,494.09
Placed in Service	February 2005		
Useful Life	20		
Adjustment	5		
Replacement Year	29-30		
Remaining Life	9		



Fitness Restrooms Renovation Allowance - 2025

Asset ID	1014 Phase I	1 LS Asset Actual Cost Percent Replacement	@ \$10,000.00 \$10,000.00 100%
(Phtasaolry 1	Misc. Bld Components	Future Cost	\$11,314.08
Placed in Service	February 2005	Tutare Cost	Ψ11,511.00
Useful Life	20		
Adjustment	1		
Replacement Year	25-26		
Remaining Life	5		



Limited use of this component located in the fitness room allows a long useful life.

Pool Restrooms Renovation Allowance - 2024

		2 EA	@ \$15,000.00
Asset ID	1012	Asset Actual Cost	\$30,000.00
	Phase I	Percent Replacement	100%
Platesgolry Misc. Bld Components		Future Cost	\$33,114.39
Placed in Service	February 2005		
Useful Life	20		
Replacement Year	24-25		
Remaining Life	4		

Pool Restrooms Renovation Allowance continued...





Standing Seam Metal Roof - Clubhouse - 2034

Asset ID	1077 Phase I	8,091 SF Asset Actual Cost Percent Replacement	@ \$12.50 \$101,137.50 100%
Category	Phase I - Roofing	Future Cost	\$142,904.64
Placed in Service	February 2005		
Useful Life	30		
Replacement Year	34-35		
Remaining Life	14		



Replacement includes gutter system.

Standing Seam Metal Roof - Maintenance Bld - 2043

Asset ID	1076 Phase I	900 SF Asset Actual Cost Percent Replacement	@ \$12.50 \$11,250.00 100%
Category	Phase I - Roofing	Future Cost	\$19,851.87
Placed in Service	April 2014		
Useful Life	30		
Replacement Year	43-44		
Remaining Life	23		

Standing Seam Metal Roof - Maintenance Bld continued...



This component has not been constructed at the time of site visit. We assume that based on the plans

Buildings/Wood Ceilings - 2026

Remaining Life

@ \$14,000.00 Asset ID \$14,000.00 1002 Asset Actual Cost Percent Replacement 100% Phase I CategBhase I - Exterior Painting Future Cost \$16,235.71 Placed in Service January 2019 Useful Life Replacement Year 26-27

6





1 LS

Maintenance Building - 2027

	2,400 SF	@ \$2.00
1003	Asset Actual Cost	\$4,800.00
Phase I	Percent Replacement	100%
CategPhyase I - Exterior Painting		\$5,705.69
April 2014		
8		
6		
27-28		
7		
	Phase I for Painting April 2014 8 6	1003 Asset Actual Cost Phase I Percent Replacement for Painting Future Cost April 2014 8 6



This component has not been constructed at the time of site visit. We assume that based on the plans

Laminated Wood Flooring - Fitness Center - 2030

		820 SF	@ \$6.20
Asset ID	1078	Asset Actual Cost	\$5,084.00
	Phase I	Percent Replacement	100%
Plastegorylooring/Interior Finishes		Future Cost	\$6,507.95
Placed in Service	January 2016		
Useful Life	15		
Replacement Year	30-31		
Remaining Life	10		
Termining Diffe	10		



Fitness Equip. Partial Replace Allowance (1 year cycle) - 2020

	1 LS	@ \$3,500.00
1007	Asset Actual Cost	\$3,500.00
Phase I	Percent Replacement	100%
tures & Equipment	Future Cost	\$3,500.00
February 2016		
1		
20-21		
0		
	Phase I tures & Equipment February 2016 1 20-21	1007 Asset Actual Cost Phase I Percent Replacement tures & Equipment February 2016 1 20-21



Useful life is determined by usage and individual pieces of equipment may be replaced as needed.

Fitness Equipment Replacement Allowance - 2040

			1 LS	@ \$27,500.00
	Asset ID	1131	Asset Actual Cost	\$27,500.00
		Phase I	Percent Replacement	100%
Phase I - Category, Fixtures & Equipment		Fixtures & Equipment	Future Cost	\$45,061.95
Place	ed in Service	February 2016		
	Useful Life	25		
Replac	ement Year	40-41		
Rei	maining Life	20		

Fitness Equipment Replacement Allowance continued...



Useful life is determined by usage and individual pieces of equipment may be replaced as needed.

Fitness Room TV's - 2020

Remaining Life

ness Room 1 v s - 2020		2 EA	@ \$600.00
Asset ID	1008	Asset Actual Cost	\$1,200.00
	Phase I	Percent Replacement	100%
Phase I - Category, Fixtures & Equipment		Future Cost	\$1,200.00
Placed in Service	June 2014		
Useful Life	5		
Replacement Year	20-21		



0

Operational Budget Expense

Golf Cart - 2031		1 EA	@ \$7,200.00
Asset ID	1128	Asset Actual Cost	\$7,200.00
		Percent Replacement	100%
Phase I - Catagourg , Fi	xtures & Equipment	Future Cost	\$9,447.02
Placed in Service	January 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	11		

Office Furniture/Con	nputers - 2025	1 LS	@ \$2,200.00
Asset ID	1005	Asset Actual Cost	\$2,200.00
	Phase I	Percent Replacement	100%
Phase I - Eurogoure,	Fixtures & Equipment	Future Cost	\$2,489.10
Placed in Service	January 2020		
Useful Life	5		
Adjustment	1		
Replacement Year	25-26		
Remaining Life	5		

100%

Pool Furniture (Full Replacement) - 2024

@ \$40,000.00 1 LS 1101 \$40,000.00 Asset ID Asset Actual Cost Phase I Percent Replacement Phase I - Catentoure, Fixtures & Equipment Future Cost \$44,152.52 Placed in Service January 2005 Useful Life 20 Replacement Year 24-25 Remaining Life 4



Pool Furniture Partial Replace (1 year cycle) - 2020

Asset ID Phase I - Category, Fire Placed in Service Useful Life	February 2012	1 LS Asset Actual Cost Percent Replacement Future Cost	@ \$2,000.00 \$2,000.00 100% \$2,000.00
Replacement Year Remaining Life	20-21 0		



Heat Pump - Fitness Cen	ter 3 Ton - 2031	1 EA	@ \$5,500.00
Asset ID	1048	Asset Actual Cost	\$5,500.00
	Phase I	Percent Replacement	100%
Cat Phosy I - Mechanical Systems		Future Cost	\$7,216.48
Placed in Service	March 2020		
Useful Life	12		
Replacement Year	31-32		
Remaining Life	11		

Heat Pump - Office 1	.5 Ton - 2021	1 EA	@ \$4,500.00
Asset ID	1047	Asset Actual Cost	\$4,500.00
	Phase I	Percent Replacement	100%
Cat Phosy I	- Mechanical Systems	Future Cost	\$4,612.50
Placed in Service	February 2005		
Useful Life	12		
Adjustment	5		
Replacement Year	21-22		
Remaining Life	1		

Water Coolers - 2025		3 EA	@ \$900.00
Asset ID	1046	Asset Actual Cost	\$2,700.00
	Phase I	Percent Replacement	100%
Cat Phosy I - N	Mechanical Systems	Future Cost	\$3,054.80
Placed in Service	February 2005		
Useful Life	12		

Useful Life 12
Adjustment 9
Replacement Year 25-26
Remaining Life 5



Play Equipment Allowance - 2024

y Equipment Allo	wance - 2024	1 LS	@ \$40,000.00
Asset ID	1052	Asset Actual Cost	\$40,000.00
	Phase I	Percent Replacement	100%
Category	Phase I - Playground	Future Cost	\$44,152.52
Placed in Service	February 2005		
Useful Life	15		
Adjustment	5		
Replacement Year	24-25		
Remaining Life	4		
Replacement Year	24-25		



Post Swing 2 Bay - 2027

st Swing 2 Bay - 2	2027	1 EA	@ \$3,800.00
Asset ID	1055	Asset Actual Cost	\$3,800.00
	Phase I	Percent Replacement	100%
Category	Phase I - Playground	Future Cost	\$4,517.01
Placed in Service	July 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		



1 LS

@ \$6,300.00
\$6,300.00
100%
\$6,618.94

Shade Structure Fabric - Playground - 2022

Asset ID	1054	Asset Actual Cost
	Phase I	Percent Replacement
Category	Phase I - Playground	Future Cost
Placed in Service	August 2013	
Useful Life	10	
Replacement Year	22-23	
Remaining Life	2	



Shade Structure Frame/Fabric - Playground - 2032

Asset ID	1056 Phase I	1 LS Asset Actual Cost Percent Replacement	@ \$14,000.00 \$14,000.00 100%
Category	Phase I - Playground	Future Cost	\$18,828.44
Placed in Service	August 2013		
Useful Life	20		
Replacement Year	32-33		
Remaining Life	12		



Rebound Wall/Deck Refurbishment Allowance - 2022

		1 LS	@ \$2,000.00
Asset ID	1058	Asset Actual Cost	\$2,000.00
	Phase I	Percent Replacement	100%
Category	Phase I - Tennis Court	Future Cost	\$2,101.25
Placed in Service	August 2013		
Useful Life	8		
Adjustment	2		
Replacement Year	22-23		
Remaining Life	2		



Tennis Court Resurfacing (color coat) - 2022

		740 S Y	@ \$8.60
Asset ID	1057	Asset Actual Cost	\$6,364.00
	Phase I	Percent Replacement	100%
Category	Phase I - Tennis Court	Future Cost	\$6,686.18
Placed in Service	February 2016		
Useful Life	5		
Adjustment	2		
Replacement Year	22-23		
Remaining Life	2		



Outdoor Fitness Equipment (phase 1) - 2025

Asset ID Ca?thasser√t - 0	1051 Phase I Outdoor Fitness Trail	1 EA Asset Actual Cost Percent Replacement Future Cost	@ \$4,000.00 \$4,000.00 100% \$4,525.63
Placed in Service	January 2013		. ,
Useful Life	13		
Replacement Year	25-26		
Remaining Life	5		



Outdoor Fitness Equipment (phase 1) - 2030

Asset ID	1049 Phase I	6 EA Asset Actual Cost Percent Replacement	@ \$4,000.00 \$24,000.00 100%
Cathgory - Outdoor Fitness Trail		Future Cost	\$30,722.03
Placed in Service	January 2013		
Useful Life	18		
Replacement Year	30-31		
Remaining Life	10		





Renovation Allowance Track Repair/ Surface Replenishment Allowance - 2027

		1 LS	@ \$2,000.00
Asset ID	1050	Asset Actual Cost	\$2,000.00
	Phase I	Percent Replacement	100%
Cathgory - Outdoor Fitness Trail		Future Cost	\$2,377.37
Placed in Service	September 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		

Basketball Court Resurfacing (color coat) - 2020

		265 SY	@ \$12.00
Asset ID	1059	Asset Actual Cost	\$3,180.00
	Phase I	Percent Replacement	100%
Catego Phase I - Basketball Court		Future Cost	\$3,180.00
Placed in Service	February 2010		
Useful Life	7		
Replacement Year	20-21		
Remaining Life	0		



Asset ID 1060 Asset Actual Cost \$2,000.00 Phase I Percent Replacement 100% Categorhase I - Basketball Court Future Cost \$2,262.82

Placed in Service
Useful Life
Adjustment
Replacement Year
Remaining Life
February 2005
20
25-26
February 2005



8,521 SF

@ \$8.00

Concrete Pavers - Pool Deck - 2034

Asset ID	1020	Asset Actual Cost	\$68,168.00
	Phase I	Percent Replacement	100%
Categor P ha	ase I - Swimming Pool	Future Cost	\$96,319.60
Placed in Service	February 2005		
Useful Life	30		
Replacement Year	34-35		
Remaining Life	14		



Included patio area

Filtration Equipment Refurbish Allowance - 2034

Asset ID	1023 Phase I	1 LS Asset Actual Cost Percent Replacement	@ \$30,000.00 \$30,000.00 100%
Categor Phase I - Swimming Pool		Future Cost	\$42,389.21
Placed in Service	February 2005		
Useful Life	30		
Replacement Year	34-35		
Remaining Life	14		

Filtration Equipment Refurbish Allowance continued...



Pool Filtration Repair/Replace Allowance (1 year cycle) - 2020

		1 LS	@ \$2,000.00
Asset ID	1021	Asset Actual Cost	\$2,000.00
	Phase I	Percent Replacement	100%
Categor Phase I - Swimming Pool		Future Cost	\$2,000.00
Placed in Service	February 2005		
Useful Life	1		
Replacement Year	20-21		
Remaining Life	0		



Pool Lift - 2026

ol Lift - 2026		1 EA	@ \$3,200.00
Asset ID	1027	Asset Actual Cost	\$3,200.00
	Phase I	Percent Replacement	100%
CategorPhase I - Swimming Pool		Future Cost	\$3,711.02
Placed in Service	January 2012		
Useful Life	15		
Replacement Year	26-27		
Remaining Life	6		

Pool Lift continued...



1 LS

@ \$34,000.00

\$34,000.00

\$37,529.64

100%

Pool Play Equipment - 2024

Asset ID 1019 Asset Actual Cost Phase I Percent Replacement CategorPhase I - Swimming Pool **Future Cost** Placed in Service February 2005 Useful Life 20 Replacement Year 24-25 Remaining Life 4



Allowance for replacement

Remaining Life

Pool Repair/Resurfacing/Tile - 2027

6,780 SF @ \$14.00 Asset ID 1022 Asset Actual Cost \$94,920.00 Phase I Percent Replacement 100% CategorPhase I - Swimming Pool **Future Cost** \$112,830.05 Placed in Service January 2018 Useful Life 10 Replacement Year 27-28



Shade Structure Fabric - 2022

ade Structure Fabric -	2022	2 EA	@ \$1,200.00
Asset ID	1025	Asset Actual Cost	\$2,400.00
	Phase I	Percent Replacement	100%
Categor Phase I - Swimming Pool		Future Cost	\$2,521.50
Placed in Service	August 2013		
Useful Life	10		
Replacement Year	22-23		
Remaining Life	2		



These units were installed in August of 2013 bringing the total for Phase 1 pool to 4 units.

Shade Structure Frame/Fabric - 2037

iaue Structure Prante/Patric - 2037		2 EA	@ \$4,000.00
Asset ID	1028	Asset Actual Cost	\$8,000.00
	Phase I	Percent Replacement	100%
CategorPhase I - Swimming Pool		Future Cost	\$12,172.95
Placed in Service	August 2013		
Useful Life	25		
Replacement Year	37-38		
Remaining Life	17		



These units were installed in August of 2013 bringing the total for Phase 1 pool to 4 units.

Shade Structures Fabric - 2020

ade Structures Fabric	c - 2020	4 EA	@ \$1,200.00
Asset ID	1024	Asset Actual Cost	\$4,800.00
	Phase I	Percent Replacement	100%
CategorPhase I - Swimming Pool		Future Cost	\$4,800.00
Placed in Service	February 2005		
Useful Life	10		
Replacement Year	20-21		
Remaining Life	0		



Shade Structures	Frame/Fabric -	- 2029
-------------------------	----------------	--------

@ \$4,000.00 2 EA Asset Actual Cost Asset ID 1026 \$8,000.00 Phase I Percent Replacement 100% Categor Phase I - Swimming Pool Future Cost \$9,990.90 Placed in Service February 2005 Useful Life 25 Replacement Year 29-30 Remaining Life 9



Asphalt Mill & Overlay 1 1/2" - Parking Lot - 2037

Asset ID	1085 Phase II	840 SY Asset Actual Cost Percent Replacement	@ \$18.00 \$15,120.00 100%
Plategolfy Misc Site Components		Future Cost	\$23,006.87
Placed in Service	March 2013		
Useful Life	25		
Replacement Year	37-38		
Remaining Life	17		



Asphalt Seal Coat - l	Parking Lot - 2023	840 SY	@ \$2.00
Asset ID	1084	Asset Actual Cost	\$1,680.00
	Phase II	Percent Replacement	100%
Planegolfy-	Misc Site Components	Future Cost	\$1,809.18
Placed in Service	January 2019		
Useful Life	4		
Adjustment	1		
Replacement Year	23-24		
Remaining Life	3		

Concrete Curb - 2027		340 LF	@ \$8.95
Asset ID	1082	Asset Actual Cost	\$3,043.00
	Phase II	Percent Replacement	100%
Plaasgdty Mis	sc Site Components	Future Cost	\$3,617.17
Placed in Service	March 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		

Concrete Pavers - 2042

42	700 SF	@ \$8.00
1122	Asset Actual Cost	\$5,600.00
Phase II	Percent Replacement	100%
Plategoty- Misc Site Components		\$9,640.80
March 2013		
30		
42-43		
22		
	Phase II Misc Site Components March 2013 30 42-43	1122 Asset Actual Cost Phase II Percent Replacement Misc Site Components March 2013 30 42-43



Concrete Sidewalk Repair/Replace Allowance - 2037

		1 LS	@ \$1,000.00
Asset ID	1081	Asset Actual Cost	\$1,000.00
	Phase II	Percent Replacement	100%
Plategoty Misc Site Components		Future Cost	\$1,521.62
Placed in Service	March 2013		
Useful Life	25		
Replacement Year	37-38		
Remaining Life	17		

East Monument Sign Refurbish Allowance - 2034

Asset ID	1083 Phase II	1 LS Asset Actual Cost Percent Replacement	@ \$2,000.00 \$2,000.00 100%
Plansgdfy-	Misc Site Components	Future Cost	\$2,825.95
Placed in Service	January 2020		
Useful Life	15		
Replacement Year	34-35		
Remaining Life	14		



Exterior Signage - 2027		1 LS	@ \$5,000.00
Asset ID	1080	Asset Actual Cost	\$5,000.00
	Phase II	Percent Replacement	100%
Plaasedty Misc	Site Components	Future Cost	\$5,943.43
Placed in Service	March 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		

847 LF

@ \$41.00

100%

Aluminun Fence 4 ft. - Pool - 2029

Asset ID 1086 Asset Actual Cost \$34,727.00 Phase II Percent Replacement CategPhase II - Fencing & Gates Future Cost \$43,369.26 February 2005 Placed in Service Useful Life 25 Replacement Year 29-30 Remaining Life 9



Vinyl Privacy Fence - Pool Equipment - 2042

Asset ID	1087	80 LF Asset Actual Cost	@ \$31.00 \$2,480.00
	Phase II	Percent Replacement	100%
Categ Bhy ase II	I - Fencing & Gates	Future Cost	\$4,269.50
Placed in Service	March 2013		
Useful Life	30		
Replacement Year	42-43		
Remaining Life	22		

4 EA

100%

Light Poles - Basketball Court - 2037

@ \$3,000.00 Asset Actual Cost Asset ID 1090 \$12,000.00 Phase II Percent Replacement Category Phase II - Site Lighting Future Cost \$18,259.42 Placed in Service March 2013 Useful Life 25 Replacement Year 37-38 Remaining Life

17



Light Poles - Parking Lot - 2037

ght Poles - Parking Lo	ot - 2037	2 EA	@ \$3,500.00
Asset ID	1089	Asset Actual Cost	\$7,000.00
	Phase II	Percent Replacement	100%
Category Phas	se II - Site Lighting	Future Cost	\$10,651.33
Placed in Service	March 2013		
Useful Life	25		
Replacement Year	37-38		
Remaining Life	17		



Light Poles - Playgound - 2037

ght Poles - Playgound - 2037		5 EA	@ \$3,000.00
Asset ID	1088	Asset Actual Cost	\$15,000.00
	Phase II	Percent Replacement	100%
Category Phase II - Site Lighting		Future Cost	\$22,824.27
Placed in Service	March 2013		
Useful Life	25		
Replacement Year	37-38		
Remaining Life	17		



Pool Restrooms Renovation Allowance - 2032

Asset ID	1093 Phase II lisc. Bld Components	2 EA Asset Actual Cost Percent Replacement Future Cost	@ \$10,000.00 \$20,000.00 100% \$26,897.78
.	<u>*</u>	Tuture Cost	Ψ20,071.70
Placed in Service	March 2013		
Useful Life	20		
Replacement Year	32-33		
Remaining Life	12		





Standing Seam Metal Roof - CH/Restroom Bld - 2042

	4,120 SF	@ \$12.50
1094	Asset Actual Cost	\$51,500.00
Phase II	Percent Replacement	100%
Phase II - Roofing	Future Cost	\$88,660.93
March 2013		
30		
42-43		
22		
	Phase II Phase II - Roofing March 2013 30 42-43	1094 Asset Actual Cost Phase II - Roofing March 2013 30 42-43 Asset Actual Cost Percent Replacement Future Cost



Buildings/Pergola - 2024

Replacement Year

Remaining Life

ildings/Pergola - 2024		3,400 SF	@ \$4.10
Asset ID	1095	Asset Actual Cost	\$13,940.00
	Phase II	Percent Replacement	100%
Categ Bhy ase II - F	Exterior Painting	Future Cost	\$15,387.15
Placed in Service	March 2017		
Useful Life	8		

24-25

4





Includes pergola, vents and and trim.

Flooring - Clubhouse - 2020

1,040 SF @ \$6.00 Asset ID 1097 Asset Actual Cost \$6,240.00 Percent Replacement 100% Phase II Future Cost Phasateleonylooring/Interior Finishes \$6,240.00 Placed in Service March 2013 Useful Life 8 Replacement Year 20-21 Remaining Life 0



District intends on replacing with viny flooring.

Interior Painting - CH/Restrooms - 2021		1 LS	@ \$5,280.00
Asset ID	1130	Asset Actual Cost	\$5,280.00
	Phase II	Percent Replacement	100%
Phsategorylooring/Interior Finishes		Future Cost	\$5,412.00
Placed in Service	March 2013		
Useful Life	7		
Adjustment	2		
Replacement Year	21-22		
Remaining Life	1		

Interior Painting - CH/Restrooms continued...



District intends on replacing with viny flooring.

Laminate Cabinets & Top - Clubhouse - 2032

Asset ID	1096 Phase II	14 LF Asset Actual Cost Percent Replacement	@ \$225.00 \$3,150.00 100%
Phaseteleofflooring/Interior Finishes		Future Cost	\$4,236.40
Placed in Service	March 2013		
Useful Life	20		
Replacement Year	32-33		
Remaining Life	12		



Pool Furniture (Full Replacement) - 2032

ool Furniture (Full Replacement) - 2032		1 LS	@ \$40,000.00
Asset ID	1117	Asset Actual Cost	\$40,000.00
	Phase II	Percent Replacement	100%
Phase IICatugoiture, Fixtures, Equipment		Future Cost	\$53,795.55
Placed in Service	February 2013		
Useful Life	20		
Replacement Year	32-33		
Remaining Life	12		



Pool Furniture Partial Replace (1 year cycle) - 2020

Asset ID	1100 Phase II	1 LS Asset Actual Cost Percent Replacement Future Cost	@ \$2,000.00 \$2,000.00 100% \$2,000.00
Phase IICatagoityre, Fixtures, Equipment Placed in Service February 2013		Future Cost	\$2,000.00
Useful Life	February 2013		
	20-21		
Replacement Year			
Remaining Life	0		



HVAC Systems - 2027

AC Systems - 2027		8 TONS	@ \$1,500.00
Asset ID	1099	Asset Actual Cost	\$12,000.00
	Phase II	Percent Replacement	100%
CalleboseyII - Mechanical Systems		Future Cost	\$14,264.23
Placed in Service	March 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		



Water Coolers - 2025

ater Coolers - 2025		3 EA	@ \$900.00
Asset ID	1098	Asset Actual Cost	\$2,700.00
	Phase II	Percent Replacement	100%
CalebaseyII - Mechanical Systems		Future Cost	\$3,054.80
Placed in Service	March 2013		
Useful Life	12		
Adjustment	1		
Replacement Year	25-26		
Remaining Life	5		



Climber - 2027

 027
 1 EA
 @ \$3,200.00

 Asset ID
 1120
 Asset Actual Cost Percent Replacement
 \$3,200.00

 Percent Replacement
 100%

 Category Phase II - Playground
 Future Cost \$3,803.79

Category Phase II - Playground
Placed in Service March 2013
Useful Life 15
Replacement Year 27-28
Remaining Life 7



Play Equipment Allowance - 2027

ay Equipment Allowance - 2027		1 LS	@ \$30,000.00
Asset ID	1106	Asset Actual Cost	\$30,000.00
	Phase II	Percent Replacement	100%
Category	Phase II - Playground	Future Cost	\$35,660.57
Placed in Service	March 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		



Post Swing One Bay - 2027

ost Swing One Bay - 2027		1 LS	@ \$2,800.00
Asset ID	1118	Asset Actual Cost	\$2,800.00
	Phase II	Percent Replacement	100%
Category	Phase II - Playground	Future Cost	\$3,328.32
Placed in Service	March 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		



Basketball Court Resurfacing (color coat) - 2021

		634 S Y	@ \$12.00
Asset ID	1105	Asset Actual Cost	\$7,608.00
	Phase II	Percent Replacement	100%
CategBhyase II - Basketball Court		Future Cost	\$7,798.20
Placed in Service	March 2013		
Useful Life	7		
Adjustment	2		
Replacement Year	21-22		
Remaining Life	1		



@ \$1,500.00

\$3,000.00

\$3,566.06

100%

2 EA

Basketball Pole & Backboard - 2027

Asset ID 1104 Asset Actual Cost
Phase II Percent Replacement
CategBhase II - Basketball Court
Placed in Service March 2013
Useful Life 15
Replacement Year 27-28
Remaining Life 7



Concrete Pavers - Pool Deck - 2042		5,501 SF	@ \$8.00
Asset ID	1115	Asset Actual Cost	\$44,008.00
	Phase II	Percent Replacement	100%
Catego Phase II - Swimming Pool		Future Cost	\$75,762.91
Placed in Service	March 2013		
Useful Life	30		
Replacement Year	42-43		
Remaining Life	22		

.

Filtration Equipment Refurbishment Allowance - 2042

		1 LS	@ \$30,000.00
Asset ID	1110	Asset Actual Cost	\$30,000.00
	Phase II	Percent Replacement	100%
Catego Phase II - Swimming Pool		Future Cost	\$51,647.14
Placed in Service	February 2013		
Useful Life	30		
Replacement Year	42-43		
Remaining Life	22		

Pergola Repair Allowance - 2020

1 Lump Sum @ \$15,000.00 Asset Actual Cost Asset ID 1129 \$15,000.00 Phase II Percent Replacement 100% CategoPhase II - Swimming Pool Future Cost \$15,000.00 Placed in Service March 2013 Useful Life Replacement Year 20-21 Remaining Life 0



Pool Filtration Repair/Replace Allowance (1 year cycle) - 2020

		1 LS	@ \$2,000.00
Asset ID	1133	Asset Actual Cost	\$2,000.00
	Phase I	Percent Replacement	100%
Catego Phase II - Swimming Pool		Future Cost	\$2,000.00
Placed in Service	February 2005		
Useful Life	1		
Replacement Year	20-21		
Remaining Life	0		



Pool Lift - 2027

ol Lift - 2027		1 EA	@ \$3,200.00
Asset ID	1114	Asset Actual Cost	\$3,200.00
	Phase II	Percent Replacement	100%
CategoPhase II - Swimming Pool		Future Cost	\$3,803.79
Placed in Service	March 2013		
Useful Life	15		
Replacement Year	27-28		
Remaining Life	7		

Pool Lift continued...



Pool Pumps & Equipment Allowance - 2020

Asset ID	1116 Phase II	1 LS Asset Actual Cost Percent Replacement	@ \$2,000.00 \$2,000.00 100%
Catego Phase II - Swimming Pool		Future Cost	\$2,000.00
Placed in Service	March 2013		
Useful Life	1		
Replacement Year	20-21		
Remaining Life	0		



5,172 SF

@ \$14.00

100%

\$72,408.00

\$76,073.65

Pool Repair/Resurfacing/Tile - 2022

Asset ID
Phase II
Phase II
Catego Phase II - Swimming Pool
Placed in Service
Useful Life
Replacement Year
Remaining Life

Asset Actual Cost
Percent Replacement
Future Cost

10
Replacement Year
22-23
Remaining Life
2



Shade Structures Fabric - 2022

ade Structures Fabric	- 2022	4 EA	@ \$1,200.00
Asset ID	1112	Asset Actual Cost	\$4,800.00
	Phase I	Percent Replacement	100%
Catego Phase II - Swimming Pool		Future Cost	\$5,043.00
Placed in Service	February 2013		
Useful Life	10		
Replacement Year	22-23		
Remaining Life	2		



@ \$4,000.00

\$16,000.00

\$24,345.89

100%

4 EA

Shade Structures Frame/Fabric - 2037

Asset ID
Phase II
Phase II
Catego Phase II - Swimming Pool
Placed in Service
Placed in Service
Service
Placed in Service
February 2013
Useful Life
25
Replacement Year
37-38
Remaining Life
17



Wood Repair/Replace - P	ergola - 2039	800 SF	@ \$22.00
Asset ID	1029	Asset Actual Cost	\$17,600.00
	Phase II	Percent Replacement	100%
Catego Phase II - Swimming Pool		Future Cost	\$28,136.24
Placed in Service	January 2020		
Useful Life	20		
Replacement Year	39-40		
Remaining Life	19		



Benches/Trash Cans/Etc Allow (1 year cycle) - 2021

		1 LS	@ \$1,000.00
Asset ID	1109	Asset Actual Cost	\$1,000.00
	Phase II	Percent Replacement	100%
Categor Pocket Park Components		Future Cost	\$1,025.00
Placed in Service	January 2020		
Useful Life	1		
Adjustment	1		
Replacement Year	21-22		
Remaining Life	1		





Light Poles - 2034		7.54	@ ¢1 400 00
Eight Foles 2091)	7 EA	@ \$1,400.00
Asset ID	1126	Asset Actual Cost	\$9,800.00
		Percent Replacement	100%
CategoiRo	cket Park Components	Future Cost	\$13,847.14
Placed in Service	February 2010		
Useful Life	25		
Replacement Year	34-35		



Picnic Pavilion - 2034

Remaining Life

273 SF @ \$30.00 Asset ID 1108 \$8,190.00 Asset Actual Cost Phase II Percent Replacement 100% CategoiRocket Park Components Future Cost \$11,572.25 Placed in Service March 2010 Useful Life 25 Replacement Year 34-35



14

Picnic Tables - Expan	ded Metal - 2029	2 EA	@ \$1,200.00
Asset ID	1127	Asset Actual Cost Percent Replacement	\$2,400.00 100%
Categor Pocket Park Components		Future Cost	\$2,997.27
Placed in Service	February 2010		
Useful Life	15		
Adjustment	5		
Replacement Year	29-30		
Remaining Life	9		



Play Equipment Allowance - 2024

Asset ID 1107
Phase II Per
Categor Rocket Park Components
Placed in Service March 2010
Useful Life 15
Replacement Year 24-25
Remaining Life 4



1

Spring Riders - 2024

Asset ID 1125

Catego Rocket Park Components
Placed in Service January 2010
Useful Life 15
Replacement Year 24-25
Remaining Life 4

2 EA @ \$800.00
Asset Actual Cost \$1,600.00
Percent Replacement 100%
Future Cost \$1,766.10



Access Control Systen

Asset ID 1006 Asset Actual Cost Phase I Percent Replacement

100% Categorymponents Not Included Future Cost Placed in Service February 2005

Access Control Systen

Asset ID	1102	Asset Actual Cost	
	Phase II	Percent Replacement	100%
Categorympon	ents Not Included	Future Cost	
Placed in Service	March 2013		
Useful Life	20		
Replacement Year	32-33		
Remaining Life	12		

Aluminum Flag Poles

Asset ID 1041 Asset Actual Cost

Phase I Percent Replacement 100% Categorymponents Not Included Future Cost

Placed in Service February 2005

Audio Equipment

Asset ID 1011 Asset Actual Cost
Phase I Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service July 2013

Exterior Decorative Louvers

Asset ID	1064	Asset Actual Cost	
	Phase I	Percent Replacement	100%
Categorympo	onents Not Included	Future Cost	
Placed in Service	February 2005		
Useful Life	25		
Replacement Year	29-30		
Remaining Life	9		

Exterior Doors

Asset ID 1091 Asset Actual Cost
Phase II Percent Replacement

100%

Categorymponents Not Included Future Cost
Placed in Service March 2013
No Useful Life



Exterior Fireplace & Chimney

Asset ID	1061	Asset Actual Cost	
	Phase I	Percent Replacement	100%
Categorymponents Not Included		Future Cost	
Placed in Service	February 2005		
Useful Life	10		
Replacement Year	20-21		
Remaining Life	0		

Exterior Siding/Trim

Asset ID 1071 Asset Actual Cost
Phase II Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service February 2005

Exterior Signage

Asset ID 1042 Asset Actual Cost Phase I Percent Replacement

100% Categorymponents Not Included Future Cost Placed in Service February 2005

Fitness Room Ceiling Fans

Asset ID 1067 Asset Actual Cost Phase I

Percent Replacement 100% Categorymponents Not Included Future Cost

Placed in Service February 2005

Gutters/Downspouts

Asset ID 1092 Asset Actual Cost
Phase II Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service February 2005

Interior Painting - Clubhouse/Restrooms

Asset ID 1079 Asset Actual Cost
Phase I Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service March 2013

Office Carpet & Paint Renovation

Asset ID 1075 Asset Actual Cost Phase I Percent Replacement

100% Categorymponents Not Included Future Cost Placed in Service February 2005

Patio Bar/Sink Phase 1

Asset ID 1063 Asset Actual Cost

Phase I Percent Replacement 100% Categorymponents Not Included Future Cost

Placed in Service February 2005

Pool Hand Rails

Asset ID	1074	Asset Actual Cost	
	Phase I	Percent Replacement	100%
Categorymponents Not Included		Future Cost	
Placed in Service	February 2005		
Useful Life	15		
Replacement Year	20-21		
Remaining Life	0		

Pool Shower Poles

Asset ID 1073 Asset Actual Cost
Phase I Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service February 2005

Storm Water Pond Maintenance

Asset ID 1072 Asset Actual Cost

Phase I Percent Replacement 100% Categorymponents Not Included Future Cost

Placed in Service February 2005

Street Signs

Asset ID 1132 Asset Actual Cost Percent Replacement

100%

Categorymponents Not Included Future Cost
Placed in Service February 2017

Tennis Court Net Replacement

Asset ID 1068 Asset Actual Cost Phase I

February 2005

Percent Replacement 100% Categorymponents Not Included Future Cost Placed in Service

Tennis Court Replacement

Asset ID 1070 Asset Actual Cost Percent Replacement

100%

Categorymponents Not Included Future Cost Placed in Service February 2005

Water Heater

Asset ID 1062 Asset Actual Cost
Phase I Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service February 2005

Windows

Asset ID 1065 Asset Actual Cost
Phase I Percent Replacement 100%
Categorymponents Not Included Future Cost
Placed in Service February 2005
No Useful Life

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. We recommend Full Funding if possible to avoid deferred maintenance or special assessments. Baseline Funding maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including CDD communities, Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service is our common business practice but our attention to detail, quick response and interest in client relationships continues to earn us a larger market share of work each year.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining District value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.